

Remington Arms Co., Inc.  
Product Service  
Legal Case #:7370

## Case Information

| RE#    | Date Opened | Date Opened(PS) | Date Closed | Incident Date | Pre Lit | Lit | Obsolete |
|--------|-------------|-----------------|-------------|---------------|---------|-----|----------|
| 257439 | 2/3/2012    | 2/6/2012        | 2/6/2012    |               |         |     |          |

## Customer Information

| Type     | Business | First Name | Last Name | Street                      | City       | State | Zip   | Age | Contact        |
|----------|----------|------------|-----------|-----------------------------|------------|-------|-------|-----|----------------|
| Reporter | Skeeters |            | Skeeters  | PO Box 184<br>2 E. Water St | Smithsburg | MD    | 21783 |     | W 240-329-0504 |

## Incident Information

| Claims | Codes                           | Repair Est.                        | Medical Treatment | Medical Status |
|--------|---------------------------------|------------------------------------|-------------------|----------------|
| PI     |                                 |                                    |                   |                |
| PD     | Cause:4015 Improper Maintenance |                                    | Unknown           |                |
| S      | Fired on safety release         | Concern:1007 Fired on Safe Release |                   |                |
| C      |                                 |                                    |                   |                |

2/20/12

## Firearm Information

| Mfg.           | Type               | Model/Ga.     | SKU            | Serial   | Bbl. | DOM      |
|----------------|--------------------|---------------|----------------|----------|------|----------|
| Remington      | CF/BA              | 700/3006 SPRG | n/a            | A6332191 | OI   | 7/9/1976 |
| Date Purchased | Where Purchased    | Accessories   | Original Owner |          |      |          |
|                | K MART PLYMOUTH MI | SCOPE BASE    | U              |          |      |          |

CONCERN:FSR

Ammunition Information - None Defined

Other Products Information - None Defined

## Settlement

Remington/700/CF/BA

| Settlement  | Release of Claims       | Release Date            | Reimbursement | Cash Settlement | Reim. Date APV | Cash Date APV |
|---|-------------------------|-------------------------|---------------|-----------------|----------------|---------------|
| Per Ilion, replace TPA, clean, test at BLSM price |                         |                         |               |                 |                |               |
|   | Repair/Replacement Cost | Repair/Replacement Date |               |                 |                |               |
|   | 30.40                   | 2/20/2012               |               |                 |                |               |

2/20/12 Per Ilion, trigger assm very dirty, parts work sluggish. Replace TPA, clean, test at BLSM price.cm

## Examination[Remington/CF/BA]

| Part        | Sub-Part               | Code                       | Comment       |
|-------------|------------------------|----------------------------|---------------|
| Examination | Examiner               |                            | B.TRAVIS      |
|             | Exam Date              |                            | 2/6/2012      |
|             | Product Type           |                            | RF            |
|             | Action Type            |                            | A             |
|             | Assigned To            |                            | T.NAGLE       |
| Cause       | 4015                   | Improper Maintenance       |               |
| Barrel      | Description            |                            | 22" 3006 SPRG |
|             | Date Code              |                            | OI            |
|             | Bore Plugged           | False                      |               |
|             | Bulged                 | False                      |               |
|             | Fired                  | False                      |               |
|             | Fired while Obstructed |                            |               |
|             | Muzzle/Crown           | Slightly Worn, Functioning |               |

|                          |                    |                                |   |
|--------------------------|--------------------|--------------------------------|---|
|                          | Condition          |                                |   |
| Bolt                     | Firing Pin         | Slightly Worn; Functioning     |   |
|                          | Shroud             | Slightly Worn; Functioning     |   |
|                          | Face               | Slightly Worn; Functioning     |   |
|                          | Handle             | Slightly Worn; Functioning     |   |
|                          | Stop               | Slightly Worn; Functioning     |   |
| Extractor                | Condition          | Slightly Worn; Functioning     |   |
|                          | Cut Condition      | Slightly Worn; Functioning     |   |
|                          | Ext/Eject Test     | False                          |   |
| Locking                  | Block Condition    | Select                         |   |
|                          | Lug Condition      | Slightly Worn; Functioning     |   |
|                          | Notch Condition    | ---Select---                   |   |
| Overall                  | Exterior Condition | Slightly Worn; Not Functioning |   |
|                          | Stock Condition    | Slightly Worn; Functioning     |   |
|                          | Fore End Condition | ---Select---                   |   |
| Receiver                 | Condition          | Slightly Worn; Functioning     |   |
|                          | Bulged             | False                          |   |
| Safety                   | Description        |                                | M700 BOLT LOCK SAFETY                           |
|                          | Function           | Like new; Functioning          |   |
|                          | Sub-Assembly       | Non-ISS                        |   |
| Sear                     | Lift               | ---Select---                   | .007  |
|                          | Notch              | Slightly Worn; Functioning     |   |
|                          | Tests              | Test Fired                     | False   |
| Feeding Test             |                    | False                          |   |
| Trigger                  | Condition          | Slightly Worn; Not Functioning | VERY DIRTY,PARTS WORK SLUGGISH WILL FOLLOW DOWN |
|                          | Pull               | ---Select---                   | 4#  |
|                          | Altered            | False                          |   |
|                          | Sub-Assembly       | M700 Bolt Lock                 |   |
| Non-Remington Components | Description        |                                | SCOPE BASE                                      |



7370



22"  
0.77/7  
4#  
1007

# SKEETERS


HARRY LEWIS  
PO BOX 184  
2 E. WATER STREET  
SMITHSBURG, MD 21783  
PHONE 240-329-0504  
FAX 240-329-0464  
FFL 8-52-043-01-4M-11449  
Buy, Sell and Trade New or Used Guns

## TRIGGER/SAFETY PROGRAM

A CUSTOMER REQUESTED HIS REMINGTON 700 30-06 SN  
A6332191 BE RETURNED UNDER THE BL SAFETY PROGRAM.  
CUSTOMER INDICATED HIS RIFLE FIRED WHEN THE SAFETY  
WAS PLACED IN THE FIRE POSITION. NO ONE WAS HURT OR  
INJURED BUT THE CUSTOMER IS CONCERNED ABOUT THE SAFE  
OPERATION AND PREFORMANCE OF HIS RIFLE.

A6332191

Model: 700



RE00257439

Thank You

*Harry R. Lewis*  
Harry Lewis  
Owner

T.A. very dirty, parts work  
Sluggish. Repaired TPA, clean  
+ most under BCP Ron B 20+

RECEIVED  
FEB 09 2012

Quote

BY:.....





