## Remington Arms Co., Inc. Product Service Legal Case #:7715

				Lega	al Case #:77	15							
Case Inform	ation												
RE#	Dat	e Opened	Opened Date Opened		d(PS) Date Closed		Incident Date			Pre Lit	Li	t	Obsolete
270763 6/7/20		7/2012	6/8/	2012	6/8/201	2							
Customer In	formatic	מפ											
Type B	Business	First Name	Last Name	Stre	et	City	State	Zip	Age		Con	tact	
Incident		Dennis	White	44-24 Crawfo	ord Dr East	Union	CT	06076		E dennisv	vhite	57@g	mail.com
Incident Info	ormation	i											
	Claims			Codes			Rep	air Est.	Medic	al Treatn	ent	Med	ical Statu
PI							_						
PD			Cause:4006	Altered Adjustm	ents or Com	ponents				T_1			
S Fires w	hen bolt	is closed	Concern:1008	Fired on Bolt Clo	osing				·	Inknown			
С													
6/14/12 Per	note on S	SR, fires when	bolt is closed.	cm									
Firearm Info	rmation												
Mfg.			Туре		M	lodel/Ga	_		SKU	Sei	rial	Bbl.	DOM
Remington			CF/BA			700/2506 REN			M n/a			KT	5/1/1970
Date Purchased			Where Purchased			Accessories			nal Own	er			
		!ERNARI	GITLIN HAF	RTFORD CONN	MUZ	ZLE BR	AKE		U				
CONCERN:	FBC												
Ammunition	Informa	tion - None D	efined										
Other Produc	cts Infor	nation - None	Defined										
Settlement													
				Remin	gton/700/CF	/BA							
S.	ettlemen		Release of C	·	elease Date		i b	sement	Cas	sh Re	im. I	)ate	Cash Dat
Per Ilion, re			Release of C	iaims K	eicase Date	Re	im bur	sement	Settler	ment	APV	7	APV
	BLSM												
		3	Repair/Replac Cost	ement Repai	ir/Replacem Date	ent							
			29.44		6/14/2012								
6/14/12 Per l	lion, tris	ger assm set s		Trigger no return		v. Reniac	e TPA.	clean 1	est at RI	.SM price	cm		
		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,											
Examination	Reming	ton/CF/BA]											
					<del></del>								
]	Part		Sub-Part		Code				<del></del>	Commen	t		
		Exam	iner				B.3	RAVIS					
Examination		Exam	Date				6/8	/2012					
		Produ	ct Type				RF						
		( <del></del>	n Type				A						
			ned To				T.1	IAGLE					
Cours			<del>*</del>	Altered Ad	justments or		$\neg$						
Cause		4006		Componen									
		Descr	iption				24"	2506 R	EM				

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=7715&Type=Case

Fired while Obstructed

Muzzle/Crown

False

False

False

Slightly Worn; Functioning

Description
Date Code
Bore Plugged

Bulged

Fired

Barrel

6/14/2012

	Condition	_	$oldsymbol{ol}}}}}}}}}}}}}}}}}}$					
	Firing Pin	Slightly Worn; Functioning						
	Shroud	Slightly Worn; Functioning	7					
Bolt	Face	Slightly Worn; Functioning						
	Handle	Slightly Worn; Functioning	7					
	Stop	Slightly Worn; Functioning	7					
	Condition	Slightly Worn; Functioning	7					
Extractor	Cut Condition	Slightly Worn; Functioning						
	Ext/Eject Test	False						
	Block Condition	Select	7					
Locking	Lug Condition	Worn; Functioning						
	Notch Condition	Select						
	Exterior Condition	Slightly Worn; Not Functioning						
Overall	Stock Condition	Slightly Worn; Functioning	]					
	Fore End Condition	Select						
Receiver	Condition	Slightly Worn; Functioning						
Receiver	Bulged	False						
	Description		M/700 BOLT LOCK SAFETY					
Safety	Function	Like new; Functioning						
	Sub-Assembly	Non-ISS						
	Lift	Select	.010					
Scar	Notch	Slightly Worn; Functioning						
	Tests	Test Fired	False					
Feeding Test	100	False						
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING WILL FOLLOW DOWN					
Trigger	Pull	Select	2.5#					
<del></del>	Altered	True	SET SCREWS ALTERED					
	Sub-Assembly	M/700 Bolt Lock						
Non-Remington Components	Description		MUZZLE BRAKE					

Remington Service Service Request Madison, NC 27025-0700



010

Parts and Repairs: P:800-243-9700/F:336-548-7801 www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are n serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEAST RET.

Service Request Number / Description

SR00017726

6337703

Model 700

Customer: DENNIS WHITE

44-24 CRAWFORD DR EAST UNION, CT 06076 US

Email: denniswhite67@gmail.com

Date of Request 04/18/2012 Date Printed04/25/2012

Destination: Arms Services 14 Hoefler Ave

Lion, NY 13357 US

Email:

Your request for service on the item(s) will be evaluated by our repairman. You will be contacted with an estimate before work is performed.

Reason For Return

M240 - BOLT LOCK SAFETY MODIFICATION M310 - PERFORM SAFETY CHECKS ON TRIGGER ASSEMBLY

Service Request Section fires when bolt is closed

Parts And Service Details

Material Type

Description

Warranty

Price Disc Amount

T.A. set screws Altered.

TRIG. NOT RETURNING PROPERLY.

Mehan TPA, Cleant Test

under BCP for & 20. T.

Sub Total: Est Sales Tax:

.00

**Grand Total:** 

\$.00

of2

4/25/2012 11:47 AM









