Page 1 of 2 PrintDisplay

> Remington Arms Co., Inc. Product Service

				Legal Case #:84						
Case Inform	nation			Legar Case	.0					
RE# 295180	Date C	-	Date Opened(PS) 1/8/2013	Date Clos 1/15/201		ent Date	Pı	e Lit	Lit	Obsolete
Customer I		-010	.,0,2015	17 13720						
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age	(Contact
Incident		Louis F	Turner	19417 Par Dr	Lawrenceburg	IN	47025	J	H 51	3-505-5252
Incident In	formation									
	Claims		C	odes	Repair	Est. M	edical T	reatme	ent M	edical Status
ΡΙ					•					
PD		(Cause:4038 Could	Not Duplicate Cor	icern					
safety	vhen releasin	or the	Concern:1007 Fired	Unknown						
С										
to fire it un range, flipp	til 12/22/12. bed the safety		e was hesitant to us be zero the scope and by itself.cm							
Firearm Inf										
Mfg		Ty			SKU	_		bl.		DOM
Reming Date Purc	•	CF/I Where Pu		700/223 REM Accessories	84600 Original Ow		156113	LG 2	/27/2012	2 8:21:01 AM
Date Fure			ERCENTER 1510	TWO PIECE BAS	-	uer				
CONCERN		UESTS REFUI			 0					
		on - None Defination - None Def		D	~ A) A		J. 11.00			
				Remington/700/Cl	·/BA					Cash
•	Settlement		Release of Claims	Release D	ate Reimbu	rsement	Casi Settlen		Reim Date Al	Dota
2			Repair/Replacemen Cost 46.44	t Repair/Replace Date 1/15/201						
1/15/13 Hid	on could not	dunlicate conce	rn. Replace TPA, cle			dence in	rifle.cm			
					,					
Examination	on[Remingto	n/CF/BA]	<u></u>							
P ₂	art	9	Sub-Part		Code				Com	ment
<u> </u>		Examiner						B.TR	AVIS	
	:	Exam Date						1/8/2		
Examinati	*	roduct Type						RF		
		Action Type						Α		
1	 =									

Part	Sub-Part	Code	Comment
	Examiner		B.TRAVIS
Examination	Exam Date		1/8/2012
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
	Description		24" 223 REM
	Date Code		LG
	Bore Plugged	False	

	Bulged	False	
Barrel	Fired	False	
Barrer	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	BRASS WASH
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Reœiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
G C .	Description		XMP SAFETY
Safety	Function	Like new; Functioning	
Sear	Lift	Select	.012
	Notch	Slightly Worn; Functioning	
	T	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
Tricara	Pull	Select	3.5#
Trigger	Altered	False	
	Sub-Assembly	X-Mark Pro	

Service Request

Remington Service PO Ben 700



Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700 F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to inture the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number	Serial Number / Description		Date o	f Request:	12,28 0	012
SR00039871	G7156113	8446,	Date	Printed:	12 28 2	012
Customer: LOU TURNER 19417 PAR DRIVE LAWRENCEBURG, D	Model 700	Destination: Arms Ser 14 Hoefte llren, NY				• .
Email: littdebee @aol.com	i	Email:				
	he item(s) will be evaluated by our repairman to		warranty policy.	lf it is your fu	ilir muse	be ——
repaired and returned. If not	, you will be contacted with an estimate before w	ork at performed				
Reason For Return M310 - PERFORM SAFE	ETY CHECKS ON TRIGGER ASSEMBLY	·				
Service Request Section						
rifle fired when safet, taken	eff			e		
Parts And Service Details						
Material Type	Description	Qtr Warra Needed	nty	Price	Disc	Amount

5G7156113

Model:

THIS IS NOT AN DIVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: Est Sales Tax: .00 .00

Grand Total:

5.00

D 2	ECEIVE JAN 092013					
I	JAN	0	9	2013		
B.	٧.					

Remington Firearms Company ARMS Services 14 Hoefler Ave. Ilion, NY. 13357 Louis F. Turner 19417 Par Drive Lawrenceburg, In. 47025 513-505-5252 ©

To Whom This May Concern,

On 11-14-12, I purchased a model 700 ADL from Walmart Co. in Florence, Ky. Four days after that, I noticed that sliding the bolt into battery sounded and felt like dragging apiece of metal across a concrete sidewalk. Besides that, when a round was chambered, some burrs in the chamber gouged the case walls...so severely that I was hesitant to use them.

I spoke to David at the repair number and he said this was not acceptable and that I should send the rifle back for rework. Three weeks later, I received the rifle back and all seemed to be well. Not So!

Due to my schedule, I wasn't able to test fire the rifle until 12-22-12. I was going to zero the scope and when I got into position, I put the safety on "Safe" and loaded the chamber with one .223 round. I then aimed down range and flipped the safety "Off". The rifle fired by itself when I did that. Luckily, I knew enough not to point the muzzle at anything but the ground until I'm on target. This could have been very serious!

I have wanted to own a Remington 700 since my exposure to them in Viet Nam. I can't believe that I should be having this many quality and safety issues with your product. Please repair whatever caused this latest problem and have someone inspect the remaining quality points for my rifle.

I'm afraid that if there are any other problems, I'm going to ask for a refund and I'll have to get something from a different manufacturer.

Thank you,

Louis Tyrner



(859) 282 - 8333

MANAGER RYAN CURTIS
7625 DUERING DR
FLORENCE KY 41042

ST# 1510 OP# 00006707 TE# 97 TR# 05571

LAYAWAY SALE
LOUIS TURNER
19417 PAR DR

LAWRENCEBURG IN 47025
513-505-5252

REDACTED CUSTOMER ID # 6006431510704963

Holiday Layaway

'AYAWAY FEE 060538804147 5.00 N REARMS -004770084600 111.00 X 422.00 SUBTOTAL TAX 1 6.000 % 25.02 TOTAL 447.02 DEPOSIT 195.00 LWY OPEN FEE NEW BALANCE 5.66 247.02 HCARD TEND 200.00

> **** *** *** 8584 S # 040525 231000790788 VAL # 51003126

11/05/12 11:15:32

CHANGE

0.00

You have placed the above item(s) on layaway, under the following terms:

- 1. You will be charged a Layaway Open Fee of \$5.00 plus applicable sale tax when you open your layaway account. THE LAYAWAY OPEN FEE WILL BE RETURNED TO YOU ON A WALMART SHOPPING CARD IF YOU PAY OFF THE BALANCE DUE ON YOUR LAYAWAY OPCOUNT AND PICK UP YOUR ITEMS DUE THE REGULAR BUSINESS HOURS ON OR REFIRE THE DUE DATE, EXCEPT IN THE STATES OF CA, CO, MA, ME, MT, NJ, OR AND WA WHERE THE LAYAWAY OPEN FEE WILL BE RETURNED TO YOU TN CASH, IF SALES TAX WAS CHARGED ON THE LAYAWAY OPEN FEE, THE TAX WILL BE REFUNDED TO YOU AS A CREDIT AGAINST YOUR BALANCE DUE. The \$5.00 Layaway Open Fee will not be applied to the balance of your account when you pay off your layaway account when you pay off your layaway account. Fee of \$5.00 plus applicable sale tax account.
- 2. A Down Payment of \$10.00 or 10% of the purchase price of the Items placed in your layaway account, whichever is areater, will be collected at the time you open your layaway account. If additional items are later added to your layaway account and the initial Down Payment plus eayments pade to date do not Plus payments made to date do not equal 10% of the purchase price of all the Items them in your layaway account, an additional Bown Payment will be required.
- Items in your layaway assount will be held at this store, and may be picked up upon payment of the Balance

Save money. Live better.

ST# 1510 OP# 00006177 TE# 77 TR# 07634
VOILIED ENTRY
LAYAMAY FEE 060538804147 5.00-N
SHOP CARD 007874222273 5.00 0

LAYAWAY PAID OUT

LUT ACCT REDACTED

CUSTOHER ID # 6006431510704963

Holiday Layaway

ϝ╇첉쪍뵔첉쬯칊풁ᅷည╄┾쪞뭙쒖쪞쑵춖춖팾촺쳁┺쭞헕벍裔쨢쪞쳪襘સ믶뭙쬵杂췙뚓륁첉 147.02 SUBTOTAL TOTAL 147.02 147.02 HCARD TEND

**** **** **** 0650 S ACCUMENT # APPROVAL # 057126 REF # 231900467399

11/14/12 15:52:09

CHANGE DUE

LAYAWAY PICKUF

BIN LOCATIONS 6101

FIREARMS

004770084600 # LUY ITEKS_1 417.00 X

LAYAWAY PYHT NEW BALANCE

Please note:

- i. Huntiler copy of the layaway agreement or a statement of your account will be provided upon request.
- 2. IF YOU DO NOT PAY OFF THE BALANCE DUE ON YOUR LAYAWAY ACCOUNT. AND PICK UP YOUR LAYAWAY ITEMS DURING REGULAR BUSINESS HOURS ON OR BEFORE DECEMBER 14, 2012 (12/14/2012), THEN YOU HAVE CANCELLED YOUR LAYAWAY ACCOUNT.


3. IF YOU CANCEL YOUR LAYAWAY ACCOUNT:

UTLL BE RETURNED TO INVENTORY AND MAY
NOT BE AVAILABLE FOR PURCHASE

YOUR DOWN PAYMENTAND PAYMENTS MADE

LET BE RECIDEDED

HT: BE REFUNDED YOUR LAN



Save money. Live better.

(859) 282 - 8333

MANAGER RYAN CURTIS

7625 DEERING DR

FLORENCE KY 41042

ST# 1513 CP# COLORECC TE# 97 TR# 06152

LAYAWAY PAYMENT

LOUIS TURNER

LIMY OFFT

LWY ACCT

REDACTED

CUSTOMER ID # 6006431510704963

Holiday Layaway

PREV BAL 247.02 100.00 PAYMENT . NEW BALANCE 147.02

CASH TEND CHANGE DUE 100.00

Piesse note:

- 1. Another copy of the layaway agreement or a statement of your account will be provided upon request.
- 2. IF YOU DO NOT PAY OFF THE BALANCE DUE ON YOUR LAYAWAY ACCOUNT AND PICK UP YOUR LAYAWAY TIEMS DURING REGIZED BUSINESS HOURS ON OR BEFORE DECEMBER 14, 2012 (12/14/2012), THEN YOU HAVE CANCELLED YOUR LAYAWAY ACCOUNT.
- 3. IF YOU CANCEL YOUR LAYAWAY ACCOUNT:

ALL ITEMS IN YOUR LAYAWAY ACCOUNT WILL BE RETURNED TO INVENTORY AND MAY NOT BE AVAILABLE FOR PURCHASE

YOUR PAILTNEE FOR PURCHASE

YOUR PAYMENTS MADE

TO SEE THE LAYOUR ASSESSED PROVIDED

TO SEE THE LAYOUR THE LAYOUR SALES TAX
ON THE OPEN FEE WILL BE REFUNDED

***************** TRANSACTION TOTAL LAYAUAY PAYMENTS RECEIPT REFUND VALUE

100.00 100.00-0.00



Find low prices on the so. t the Walmart app. Call **UMT. 11/14/12 15:15:28

CUSTOMER COPY

