# Remington Arms Co., Inc. Product Service Legal Case #:9598

				l Case #:9598							
Case Informa	tion										
RE# D	ate Opened	Date Op	ened(PS)	Date Closed	Incident Date	e Pre Lit	t Lit Obsole				
329543 12/4/2013 1		12/5	/2013	12/5/2013							
Customer Infe	ormation										
Type	Business	First Name	Last Name	Street	City Sta	te Zip A	ge Contact				
Reporter	Gander Mountain	Attn: Smithy	Gander Mountain	1640 Parker Way	Opelika Al	L 36801	W 651-735 6101				
Incident Infor	rmation										
Claims		Code	s	Repai	Repair Est. Medical Treatment Medical Statu						
Ρĺ											
PD C	ause:4006	Altered Adju	stments or Cor	nponents	1 1	nknown					
S FBC C	oncem:1008	Fired on Bolt	Closing		O.	IIMIIOWII					
C Gander Moundf	ntain sent gui	n into Ilion. Re	eason for Retu	rn: Customer state	ed gun will disc	charge wher	n closing the bo				
Firearm Infor	mation										
Mfg.	T	уре	Model/Ga	. SKU	Serial	Bbl.	DOM				
Remingtor	ı CI	F/BA	770/3006 SPI	RG 85633	3 714256	17 BC 1/	1/25/2008 7:47:26 AM				
Date Purchased	Where 1	Where Purchased Acce		s Origin Owne							
		PORTS, SO LC	COPE,RINGS,	BASE U							
CONCERN:	FBC										
		- None Define on - None Defi									
			Reming	gton/770/CF/BA							
Settlement	Releas	e of Claims	Release	e Date Rein	nbursement	Cash Settlement	Reim. Ca Date Da APV AF				
Quote to repa											
	-	Replacement Cost	Repair/Re <sub>l</sub> Da								
	te. df 12/11/			ng under sear. Car er emailed the quo							
Examination[	Remington/0	CF/BA]									
	1										
ľ	ll .	1			II						

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9598&Type... 12/27/2013

PrintDisplay Page 2 of 3

Part	Sub-Part	Code	Comment				
	Examiner	]	B.TRAVIS				
Examination	Exam Date	]	12/5/2013				
	Product Type	]	RF				
	Action Type	]	A				
	Assigned To	]	S.NICHOLS				
Cause	4006	Altered Adjustments or Components					
	Description		22" 3006 SPRG				
	Date Code	]	BC				
	Bore Plugged	False					
Barrel	Bulged	False					
Dallel	Fired	False					
	Fired while Obstructed		_				
	Muzzle/Crown Condition	Slightly Worn; Functioning					
	Firing Pin	Slightly Worn; Functioning					
	Shroud	Slightly Worn; Functioning					
Bolt	Face	Slightly Worn; Functioning	1				
	Handle	Slightly Worn; Functioning	1				
	Stop	Slightly Worn; Functioning	]				
	Condition	Slightly Worn; Functioning					
Extractor	Cut Condition	Slightly Worn; Functioning					
	Ext/Eject Test	False					
	Block Condition	Select	<u></u>				
Locking	Lug Condition	Slightly Worn; Functioning					
	Notch Condition	Select					
	Condition	Select					
Magazine	Box Condition	Slightly Worn; Functioning					
	Exterior Condition	Slightly Worn; Not Functioning	1				
Overall	Stock Condition	Slightly Worn; Functioning	1				
	Fore End Condition	Select					
Receiver	Condition	Slightly Worn; Functioning	Ī ·				
	Bulged	False					
Safety	Description		STANDARD SAFETY				
	Function	Like new; Functioning					
Sear	Lift	Select	N/A				
	Notch	Slightly Worn; Functioning					
		Test Fired	False				
Feeding Test	Tests	False					
	Condition	Slightly Worn; Not Functioning	TRIG NOT RETURNING UNDER SEAR				
,	Pull	Select	N/A				

http://cps03sp01.remington.com:99/Remington\_PSA/PrintDisplay.aspx?ID=9598&Type... 12/27/2013

Trigger	Altered	True	SET SCREWS ALTERED			
	Sub-Assembly	Other Remington				

## Quotation

#### Remington Service PO Box 700

Madison, NC 27025-0700

Estimating Report

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remington.com

All PRICES QUOTED ARE IN EXCHANGE FOR REPLACED PARTS.

THIS IS NOT AN INVOICE. THIS IS AN ESTIMATE TO REPAIR, RECONDITION, OR REPLACE THE ITEM(S) DESCRIBED BELOW. IF THIS IS SATISFACTORY, PLEASE APPROVE BY SIGNING BELOW AND RETURNING TO THE ABOVE ADDRESS. REPAIR TO TAKE APPROXIMATELY (6) WEEKS AFTER RECEIPT OF APPROVAL. IF WE DO NOT RECEIVE YOUR APPROVAL IN 21 DAYS, WE WILL RETURN THE ITEM(S) AS RECEIVED, POSTAGE DUE.

•					Date Rec		12/04/2		
				Estimate		12/05/2			
		Model //U Center Fire Callocr: 30 -00 SPRG			Date Pri	itea:	12/27/2	.013	
Customer:			Reti	urn To:					
GANDER MO		GANDER MOUNTAIN							
ATTN ASHLI				1640 PARKER OPELIKA, AL					
180 E 5TH ST SUITE 1300 SAINT PAUL, MN 55101 US				OI ELIKA, AL	30001 03				
Please Circle One									
VISA MC	DISCOV	VER Card No.		Ex	D.Date				
VISA MC DISCOVER Card No.         Exp.Date           Open Account: R         PO Number:									
Approval Signatur	re:				_ Date:				
Daytime Phone	e: (	) Time to Ca	dl:						
lf you desire	e any chang	ge, please use the reverse side for your comments and Problem		box.					
Reported			und						
	ARD TO P			WARD TO PRO	DUCT SERV	ICE FOR	INSPE	CTION	
		Technician Con							
	set screws a	altered.trigger is not returning under sear properly.ca	n offer to re	eplace trigger as:	sembly,check	over and t	est fire	at 1/2	
normal cost.		ECTIVITY ( COD IN )		NOT !					
Material	Туре	ESTIMATE (note: C.O.D./Shipping and Handlin Description	g Charges : Oty	are NOT Includ Warranty	led in this Qu Qty		Disc	Amount	
112461141	JPC	2000 pton	Needed	**************************************	From Inv	11100	Disc	Allibuit	
F301265	Part	710 REC. INSERT ASSB. COMPLETE	1	Billable	1	60.00	50	30.00	
4000114	Service	GR-SHIPPING & HANDLING (GUN REPAIR	1)	Billable	1	17.00	0	17.00	
4000119	Service	GR-TEST	1	Billable	1	23.00	50	11.50	
					Sub	Total:		58.50	
					Est S	Sales Tax:		1.95	
					Grai	nd Total:		\$60.45	



# **Service Request**

Service Order # 213

#### **RETURN SHIP TO:**

Gander Mountain, FFL# 1-63-081-01-5K-04702

Attn: Gun Parts Dept. 1640 Parker Way Opelika, AL 36801

### SHIPPED TO VENDOR/STORE:

Remington ArmsCO INC FFL#6-16-00727 14 Hoefler Ave

Ilion, NY 13357 Attn: Warranty

Date Shipped: 11/28/2013

Phone: (111) 111-1111

#### FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Model:

Rifle Type:

Cal/Ga.: 30-06

Serial Number: 71425617

Cased?:

#### **DESCRIPTION OF ITEM RETURNED:**

Remington 770 Bolt Action Rifle Setrial #71425617

#### **REASON FOR RETURN:**

Customer returned guin stating that thegun will dicharge when the bolt is closed. "Slam Fire"

#### ATTENTION VENDOR

Please contact me with any questions or concerns.

**Smithy** (651) 735-6101

#### **BILLING INFORMATION:**

Please include the service order number on all invoices and correspondence: SHIP TO ABOVE ADDRESS

Forward all invoices to:

180 E. Fifth Street Suite 1300 St. Paul, MN 55101

1425617



T.A. set screws Alt. Trig. Not pet. and SLAN. CAN offen to py. T.A. check oneue + rest At 1/2 cost







