Remington Arms Co., Inc. Product Service Legal Case #:8685

Case Information

RE# Date Opened Date Opened(PS) Date Closed Incident Date Pre Lit Lit Obsolete

303887 3/7/2013 3/8/2013 3/8/2013

Customer Information

Type Business First Name Last Name Street City State Zip Age Contact

Incident Paul Peper E4138 Pierce La Valle WI 53941 E plpeper@hotmail.com

Incident Information

Claims Codes Repair Est. Medical Medical Treatment Status

ΡI

PD Cause: 4038 Could Not Duplicate

S Delayed firing Concern Unknown

S Delayed firing Concern:1023 Delayed Firing - Firearms

3/14/13 Per note on SR, gun didn't go off when he pulled the trigger but then he tried to work the bolt back and the gun went off without pulling the trigger.cm

Firearm Information

 Mfg.
 Type
 Model/Ga.
 SKU
 Serial Bbl.
 DOM

 Remington
 CF/BA
 770/270 WIN
 85632
 71495840 RC
 11/17/2008 6:05:50 AM

Date Purchased Accessories Original Owner
GANDER WAREHOUSE SCOPE

GANDER WAREHOUSE SCOPE #1/Leban BASE

CONCERN: DELAYED FIRING

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/770/CF/BA

Settlement Release of Claims Release Date Reimbursement Cash Settlement Release Date Reimbursement Release Date Relea

As a gesture of goodwill, replace TPA, clean and test at no charge

Repair/Replacement Repair/Replacement Cost Date

41.15

41.15 3/14/2013

3/14/13 Per Ilion, could not duplicate concern. As a gesture of goodwill, replace TPA, clean and test at no charge.cm

Examination[Remington/CF/BA]

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=8685&Type=... 2/14/2014

PrintDisplay Page 2 of 3

| Part | Sub-Part | Code | Comment |
|--------------|------------------------|-----------------------------|-----------------|
| Examination | Examiner | | B.TRAVIS |
| | Exam Date | | 3/8/2013 |
| | Product Type | | RF |
| | Action Type | | A |
| | Assigned To | | S.NICHOLS |
| Cause | 4038 | Could Not Duplicate Concern | |
| Barrel | Description | | 22" 270 WIN |
| | Date Code | | RC |
| | Bore Plugged | False | |
| | Bulged | False | - |
| | Fired | False | |
| | Fired while Obstructed | | |
| | Muzzle/Crown Condition | Slightly Worn; Functioning | |
| Bolt | Firing Pin | Slightly Worn; Functioning | |
| | Shroud | Slightly Worn; Functioning | |
| | Face | Slightly Worn; Functioning | |
| | Handle | Slightly Worn; Functioning | |
| | Stop | Slightly Worn; Functioning | |
| Extractor | Condition | Slightly Worn; Functioning | |
| | Cut Condition | Slightly Worn; Functioning | |
| | Ext/Eject Test | False | |
| Locking | Block Condition | Select | |
| | Lug Condition | Slightly Worn; Functioning | |
| | Notch Condition | Select | |
| Magazine | Condition | Select | |
| | Box Condition | Slightly Worn; Functioning | |
| Overall | Exterior Condition | Slightly Worn; Functioning | |
| | Stock Condition | Slightly Worn; Functioning | |
| | Fore End Condition | Select | |
| Receiver | Condition | Slightly Worn; Functioning | Ħ |
| | Bulged | False | |
| Safety | Description | | STANDARD SAFETY |
| | Function | Like new; Functioning | |
| Sear | Lift | Select | N/A |
| | Notch | Slightly Worn; Functioning | |
| | T+- | Test Fired | False |
| Feeding Test | Tests | False | |
| Trigger | Condition | Slightly Worn; Functioning | |
| | Pull | Select | 4# |
| | Altered | False | SEALANT PRESANT |
| | | | |

http://cps03sp01.remington.com:99/Remington_PSA/PrintDisplay.aspx?ID=8685&Type=... 2/14/2014

Sub-Assembly Other Remington

Service Request

Remington Service PO Box 700



02/14/2013

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.remineton.com

This document is a monmary of your request for service. Please review the document for mouracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

.25" RCH/O

Service Request Number | Serial Number / Description SR00045256 71495840

Model 770 RIFLE Caliber 270

Customer: PAUL PEPER E 4138 PIERCE

LA VALLE, WI 53941 US

Date of Request: Date Printed: 02/14/2013

Arms Services

14 Hoefler Ave Rion, NY 13357 US

Email: plpeper@hotmail.com

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Phone 608-985-7136

Reason For Return

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

M295 - EVALUATE AND REPAIR SAFETY INSP.

Service Request Section

Gun didn't go off, when he pulled the trigger, but then he tried to work the bolt back, and the gun went off, without pulling the trigger.

Parts And Service Details Type

Description

THE IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Qtv Needed

Price Disc Amount

Model:



NAR 1 2 2013

could not Jup concern. As A Good-willceskyne willing, TPA, CU AN+ TOST

260974

Sub Total: Est Sales Tax: .00 .00

Grand Total:

\$.00





