Remington Arms Co., Inc. Product Service Legal Case #:8810

Case Information

RE# **Date Opened** 4/16/2013 308112

Date Opened(PS) 4/17/2013

Wolbeck

Date Closed 4/18/2013

Incident Date

Pre Lit Lit Obsolete

Customer Information

Business First Name Type

Last Name Street City State Zip TX

Contact

H 806-790-6402 E dwolbeck@live.com

Incident Information

Incident

Claims

Douglas

Codes

Repair Est.

79423

Age

Medical Treatment Medical Status

ΡI

PD

Fired on Bolt Cause:4056

2718 109th

Opening

Lubbock

Does not fire when pulling trigger but when opening bolt

Fired on Bolt Concern:1020 Opening

Unknown

C

4/18/13 Per note on SR, fails to fire but fires when touching the bolt.cm

Firearm Information

Mfg.

Type

Model/Ga.

SKU

Serial Bbl. DOM

Remington

CF/BA

770/243 WIN

85651 M71852755 EG 10/30/2012 9:34:47 ΑM

Date Purchased

Where Purchased ACADEMY SPORTS &

OUTDOORS

Accessories **SCOPE** BASE

Original Owner

U

CONCERN: FIRES WHEN TOUCHING BOLT

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/770/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Cash

Reim. Settlement Date APV Cash Date APV

Replacing with new 85651 on SNC order

Repair/Replacement Repair/Replacement

Cost

Date

136.80

4/18/2013

4/18/13 Called owner to let him know we would be replacing and to get FFL info.cm 4/18 FFL is Academy in Lubbock. Spoke with Tori and she approved the shipment.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment						
	Examiner		B.TRAVIS						
	Exam Date		4/17/2013						
	Exam Date		4/11/2013						

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8810&Type=Case

4/18/2013

PrintDisplay Page 2 of 3

ı	Product Type	j	RF							
Examination	Action Type]	A							
	Assigned To]	S.NICHOLS							
Cause	4056	Fired on Bolt Opening	WHEN BOLT IS CLOSED BRISKLY THEN TRIGGER PULLED IT WILL NOT FIRE UNTIL BOLT IS RAISED.							
	Description		22" 243 WIN							
	Date Code]	EG							
	Bore Plugged	False								
 -	Bulged	False								
Barrel	Fired	False								
	Fired while Obstructed		_							
	Muzzle/Crown Condition	Slightly Worn; Functioning								
	Firing Pin	Slightly Worn; Functioning								
i	Shroud	Slightly Worn; Functioning								
Bolt	Face	Slightly Worn; Functioning								
	Handle	Slightly Worn; Functioning								
	Stop	Slightly Worn; Functioning								
	Condition	Slightly Worn; Functioning								
Extractor	Cut Condition	Slightly Worn; Functioning								
	Ext/Eject Test	False								
	Block Condition	Select								
Locking	Lug Condition	Slightly Worn; Functioning								
	Notch Condition	Select								
	Condition	Select								
Magazine	Box Condition	Slightly Worn; Functioning								
Overall	Exterior Condition	Slightly Worn; Functioning								
	Stock Condition	Slightly Worn; Functioning								
	Fore End Condition		_							
Receiver	Condition	Slightly Worn; Functioning								
	Bulged	False								
	Description		STANDATD SAFETY							
Safety	Function	Like new; Functioning								
	Lift	Select	N/A							
Sear	Notch	Slightly Worn; Functioning								

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8810&Type=Case

4/18/2013

		Test Fired	False					
Feeding Test	Tests	False						
	Condition	Slightly Worn; Functioning						
Trigger	Pull	Select	3.5#					
	Altered	False						
	Sub-Assembly	Other Remington						

Repair Document

Reported

Remington Service PO Box 700

Madison, NC 27025-0700

Repair Document

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

04/16/2013

04/23/2013

04/23/2013

Parts and Repairs: P:800-243-9700/F:336-548-7801

M110 - FAILS TO FIRE BUT WILL FIRED WHEN TOUCHING BOLT

M123 - FORWARD TO PRODUCT SERVICE FOR INSPECTION

www.remington.com Date Received: Repair Number Serial Number / Description RE00308112 M71852755 Estimate Date: Model 770 RIFLE Caliber: 243 Date Printed: Customer: Return To: DOUGLAS WOLBECK DOUGLAS WOLBECK 2718 109TH 2718 109TH LUBBOCK, TX 79423 US LUBBOCK, TX 79423 US Problems

Found

Technician Comments

Per request of Product Service Dept, replace with a new #85651. Replacement serial # is M71901607 shipped on order #1495070.cm

Repair information Material Description Type Bill Action Quantity











Remington Arms Company,LLC. | 870 Remington Drive | PO Box 700 | Madison, NC | 27025-0700 | USA

Sales Order Confirmation

IRS# 51-0350935 IT03373070170 IE6601509R GST 138911094RT

ACCT. NO.

BILL TO:

RAC, LLC - FIREARM SAMPLES 870 REMINGTON DRIVE

PO BOX 700

MADISON NC 27025-0700

SHIP TO:

ACADEMY SPORTS

ATTN: STORE MGR PER TORRE

M/F: TRANSFER FOR: DOUGLAS WOLBECK

806-788-4820

5802 19TH ST (@W.LOOP 289)

LUBBOCK TX 79407

PURCHASE ORDER NO.	P.O. DATE	ORDER NO.	ORDER DATE	CANCEL DATE	REQ. D	ELV.				NET WEIGHT	
Wolbeck	04/19/2013	1495070	04/19/2013		04/19/	2013					8 LB
ITEM NO.	DES	CRIPTION				ORD	QTY	UNIT	PROGRAM PR	ICE	EXT PRICE
85651	770	SS 243 WIN	22" W/SCOPI	3		1		EA	158.37		158.37
To get VPRS into :	100.	000-% 13	36.80-						1		

8850050/230145

Items total

Sample Cost

100.000 %

136.80

21.57

136.80

8311000 5 571 1150571 M71901 607

CURRENCY CODE: USD

TOTAL ORDER AMOUNT:

158.37 USD

CUST. SERV. REP: EVA DIAZ PH: 1-888-736-4867 EXT 8712 FAX: Email: Eva.Diaz@remington.com

TERMS:

NET 30 DAYS

- A. Purchases are subject to REMINGTON ARMS standard conditions of sale.
- Please review confirmation and advise us of any discrepancies with your purchase order within two business days.

PG 1 OF 3

PU Box /00

a time and a three sements and a sement and to time a ser on an analysis of a ser com-

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700 F:336-548-7801

www.remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. ENCLOSE THIS DOCUMENT WITH YOUR RETURN.

Service Request Number

Serial Number / Description

SR00049956

M71852755

Model 770 RIFLE Caliber: 243

Customer: DOUGLAS WOLBECK

2718 109TH

LUBBOCK, TX 79423 US

Date of Request: Date Printed:

04 08 2013

04 08 2013

Destination:

Anna Services

14 Hoefler Ave Ilion, NY 13357 US

Email: dwolbeck@live.com

Email:

-Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.

Reason For Return

MIIO - FAILS TO FIRE BUT WILL FIRED WHEN TOUCHING BOLT

Service Request Section

fails to fire but fires when touching bolt

Parts And Service Details Material

Description

Warranty

Price Disc Amount

3M71852755

Type



I will CONTROLT DECEL, HE MAY WANT his GUN be EVAL.

BY:----

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total:

.00

Est Sales Tax:

.00

Grand Total:

\$.00







