

Remington Arms Co., Inc.
Product Service
Legal Case #:8548

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
298537	1/29/2013	1/30/2013	1/30/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Reporter	Barrows Trading Post		Barrows Trading	6985 Woodstock Rd Box 16	Quechee	VT	05059		

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		Unknown
S	Goes off when taking off safety	Concern:1007 Fired on Safe Release		
C				

2/19/13 Per note with rifle, goes off by touching side of trigger or when taking off safety.cm

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/6MM REM	n/a	6242585	KS	5/1/1969
Date Purchased	Where Purchased	Accessories	Original Owner			
	B SMITH BOSTON MASS	TWO PIECE BASE,LEATHER STK BOOT	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Replace TPA, clean and test at BLSM program price						
	Repair/Replacement Cost	Repair/Replacement Date				
	29.04	2/19/2013				

2/19/13 Per Ilion, trigger assm set screws altered. Trigger not returning under sear. Replace TPA, clean and test at BLSM program price.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/30/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	
Barrel	Description		22" 6MM REM
	Date Code		KS
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown	Slightly Worn; Functioning	

	Condition		
Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	---Select---	TRIG NOT RETURNING PROPERLY WILL FOLLOW DOWN
	Pull	---Select---	2#
	Altered	True	SET SCREWS ALTERED SEALANT CHANGED
	Sub-Assembly	M700 Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE,LEATHER STK BOOT

BARROWS TRADING POST
6985 Woodstock Rd.
Box 16
Quechee, VT 05059

575311

8548

7211
255/66
24
1007

NAME <i>R Coley</i>	SHIP TO <i>Remington</i>
ADDRESS <i>802 295-1050</i>	ADDRESS
CITY, STATE, ZIP	CITY, STATE, ZIP

ORDER NUMBER	DEPARTMENT	SALESPERSON	WHEN SHIP	TERMS	HOW SHIP	DATE <i>1/17/13</i>
--------------	------------	-------------	-----------	-------	----------	------------------------

QUANTITY	DESCRIPTION	PRICE	AMOUNT
	<i>Dear Sirs</i>		
	<i>Enclosed find one Rem 700</i>		
	<i># 6242585</i>		
	<i>This goes off by touching side</i>		
	<i>of trigger, or just taking off safety.</i>		
	<i>Please look over and</i>		
	<i>repair as needed.</i>		
	<i>Thank you</i>		
	<i>Wayne Barrows</i>		

Serial Number: 6242585

Model: 700



RE00298537

*T.A. set screws alt. mrg
not ret. und. seal. up. rth,
clean rest und. BCP Rom
20-+*

RECEIVED
JAN 31 2013

BUYER:

BY:

adams
8100

KEEP THIS SLIP FOR REFERENCE

01-11





