

Remington Arms Co., Inc.
Product Service
Legal Case #:8827

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
308665	4/19/2013	4/22/2013	4/22/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Evan	Bartley	210 South Baywood Lane	Greenville	SC	27834		H 252-236-1105 E evanbartley@gmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4006	Altered Adjustments or Components		
S FSR	Concern:1007	Fired on Safe Release	Unknown	
C				

CSR Notes on repair: "Gun going off. When going from safe to fire". df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/22-250 REM	n/a	6834032	LZ	2/1/1975
Date Purchased	Where Purchased	Accessories	Original Owner			
	BASCHE & SAGE BAKER OREGON		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

4/23/13: Per Ilion - TA dirty, sticky & set screws altered. Replace TA, clean & test under BLM - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		4/22/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4006	Altered Adjustments or Components	IMPROPER MAINTENENCE
Barrel	Description		24" 22-250 REM HB
	Date Code		LZ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn, Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Not Functioning	BINDS
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Not Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.007
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Not Functioning	FAILS NULL TEST TRIG NOT RETURNING PROPERLY
	Pull	---Select---	5.5#
	Altered	True	NON FACTORY SEALANT
	Sub-Assembly	M/700 Bolt Lock	

Firearm Inquiry - Repair Inquiry

Repair Number: **RE00308665** Serial: 6834032 Model 700 Center Fire Caliber: 22 - 250 REM Repairman:
 Verify Repair **High Priority** Status: New 2/6/2013 12:35:14 PM

ADDRESS INFORMATION

Customer		Received from	Return To		Received from
Name:	Evan Bartley		Evan Bartley		
Address 1:	210 South Baywood Lane		210 South Baywood Lane		
Address 2:	PO Box:		PO Box:		
City:	Greenville		Greenville		
State:	SC Zip Code: 27834	Country: US	SC Zip Code: 27834	Country: US	

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone: 252 236 1105
 Fax:
 Email: evanbartley@gmail.com
 Comments:

Received Condition

Condition: Good
 Condition Notes:
 CSR Notes: GUN GOING OFF, WHEN GOING FROM SAFE TO FIRE.

Accessories Received

Code	Desc	Qty
A007	With Stud	2

RECEIVED
 APR 23 2013

Refresh Close
 BY:

T.N. dirty, sticky +
 Set screws act. and
 TOP, CLEAN + TEST UND.
 BCP foil & 20 + Q

Number: 6834032

Model: 700



RE00308665

24/7
 22/75
 5.5#
 .007









