

Remington Arms Co., Inc.
Product Service
Legal Case #:8620

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
300780	2/15/2013	2/18/2013	2/18/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Larry	Finke	785 West 400 North	Payson	UT	84651		H 801-427-7009 E finkejrlarry@rocketmail.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038	Could Not Duplicate Concern		
S FSR	Concern:1007	Fired on Safe Release	Unknown	
C				

SR# 11000 - CSR Notes on repair: Per Consumer, gun fired when he pushed the safety off. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/7 MM REM M	26933	T6208501	BP	1/9/1995
Date Purchased	Where Purchased	Accessories	Original Owner			
	BILL HICKS & CO LTD	TWO PIECE BASE	U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair @ 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

2/19/13: Per Ilion - Could not duplicate concern, TA dirty, can offer to replace TA, clean & test at 1/2 normal cost to restore confidence in rifle. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		2/18/2013
	Product Type		RF
	Action Type		A
	Assigned To		S.NICHOLS
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		24" 7 MM REM AMG SS
	Date Code		BP
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Magazine	Condition	---Select---	
	Box Condition	Missing	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	.012
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	5#
	Altered	False	SEALANT PRESANT
	Sub-Assembly	M700 Non-Bolt Lock	
Non-Remington Components	Description		TWO PIECE BASE

frmREInquiry - Repair Inquiry

Repair Number: RE00300780

Serial: T6208501 Model 700 Center Fire Caliber: 7
MM REM MAG Produced: 01/09/1995 SKU: 26933

Repairman: David Vivlamore

Verify Repair

Status: Estimating 2/15/2013 9:48:13 AM

ADDRESS INFORMATION

Customer

☒ Received from

Return To

☐ Received from

Name: LARRY FINKE

LARRY FINKE

Address 1: 785 WEST 400 NORTH

785 WEST 400 NORTH

Address 2: PO Box:

PO Box:

City: PAYSON

PAYSON

State: UT Zip Code: 84651 Country: US

UT Zip Code: 84651 Country: US

FFL: 01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Phone: 801 427 7009

Fax:

Email: finkejrlarry@rocketmail.com

Comments:

2211000

Received Condition

Good

Condition Notes

CSR Notes: PER CONSUMER, GUN FIRED WHEN HE PUSHED THE SAFETY OFF.

could not dup. concern
not T.A. dirty chamber
to pup. T.A. clean & test at
1/2 normal cost to restore
confidence in rifle.

Accessories Received

Code	Desc	Qty
A002	Less Mag Box	1
A007	With Stud	2

Refresh

Close

Serial Number:

T6208501

Model: 700



RE00300780

RECEIVED

FEB 19 2013

Monday, Feb 18 2013 3:31 PM





