

Remington Arms Co., Inc.
Product Service
Legal Case #:8780

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
307197	4/5/2013	4/8/2013	4/8/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Dave	Marlatt	10437 Lakeview Dr.	Atlanta	MI	49709		H 989-785-3092

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FBC	Concern:1008 Fired on Bolt Closing			
C				

Service Request# 48595. CSR Notes on the repair - "Sometimes fires w/o issues. Sometimes fails to fire. Has fired once when closing bolt one other time w/o pulling trigger. No property damage or injury." df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/243 WIN	26404	EG001319	KU	5/24/2000 7:53:05 AM
Date Purchased	Where Purchased	Accessories	Original Owner			
	JAY S SPORTING GOODS INC		U			

CONCERN: FBC

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair @ 1/2 normal cost						
Repair/Replacement Cost	Repair/Replacement Date					

4/9/13: Per Ilion - Could not duplicate concern. Check over competely, replace TA, clean & test at 1/2 normal cost - quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B. TRAVIS
	Exam Date		4/8/2013
	Product Type		RF
	Action Type		A
	Assigned To		S. NICHOLS
Cause	4038	Could Not Duplicate Concern	INSTALLED A BATTERY AND CHECKED FUNCTIONS
Barrel	Description		26" 243 WIN SS FL
	Date Code		KU
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn, Functioning	
	Firing Pin	Slightly Worn, Functioning	

Bolt	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		STANDARD SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	N/A
	Notch	---Select---	N/A
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	
	Pull	---Select---	3#
	Altered	False	FACTORY SEALANT PRESENT
	Sub-Assembly	Other Remington	

Repair Number: **RE00307197**

Serial: EG001319 Model 700 E-TRON Center Fire
Caliber: 243 WIN Produced: 05/24/2000 SKU: 26404

Repairman: _____

Verify Repair

High Priority

Status: New 3/21/2013 11:48:48 AM

ADDRESS INFORMATION

Customer

Received from

Return To

Received from

Name: DAVE MARLATT

Address 1: 10437 LAKEVIEW DR

Address 2: _____ PO Box: _____

City: ATLANTA

State: MI Zip Code: 49709 Country: US

Name: DAVE MARLATT

Address 1: 10437 LAKEVIEW DR

Address 2: _____ PO Box: _____

City: ATLANTA

State: MI Zip Code: 49709 Country: US

SR# 48595

FFL: _____

01011900

Contact / Condition Problems Estimate History / Status Shipping / Billing

Contact Information

Received Condition

Condition Notes

CSR Notes

Phone: 989 785 3092

Fax: _____

Email: _____

Comments: _____

Good

fire. Has fired once when closing bolt one other time w/o pulling trigger. No property damage or injury.

Accessories Received

Code	Desc	Qty
A007	With Stud	2

could not dup concern. check over completely, rep. TRA, clean test at 1/2 cost. Q

RECEIVED

APR - 9 2013

Refresh BY: _____

Close

Serial Number:

EG001319

Model: 700 E-TRON



RE00307197

J# 2641
KUS/2000







