

Remington Arms Co., Inc.
Product Service
Legal Case #:8434

Case Information

RE#	Date Opened	Date Opened(PS)	Date Closed	Incident Date	Pre Lit	Lit	Obsolete
294791	1/3/2013	1/4/2013	1/4/2013				

Customer Information

Type	Business	First Name	Last Name	Street	City	State	Zip	Age	Contact
Incident		Jose	Montoya	511 Summerwinds Dr SE	Rio Rancho	NM	87124		H 505-994-2874 E joecentury98@aol.com

Incident Information

Claims	Codes	Repair Est.	Medical Treatment	Medical Status
PI				
PD	Cause:4038 Could Not Duplicate Concern		Unknown	
S FSR	Concern:1007 Fired on Safe Release			
C				

SR# 38886 - Service Request Section: Discharges when safety is disengaged. df

Firearm Information

Mfg.	Type	Model/Ga.	SKU	Serial	Bbl.	DOM
Remington	CF/BA	700/3006 SPRG	n/a	A6652084	DQ	9/19/1978
Date Purchased	Where Purchased	Accessories	Original Owner			
	SPTS SOUTH SHREVEPORT LA		U			

CONCERN: FSR

Ammunition Information - None Defined

Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Settlement	Release of Claims	Release Date	Reimbursement	Cash Settlement	Reim. Date APV	Cash Date APV
Per Ilion - Quote to repair under BLM						
	Repair/Replacement Cost	Repair/Replacement Date				
	\$29					

1/7/13: Per Ilion - Could not duplicate concern. TA dirty. Replace TA, clean & test under BLM - Quote. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		1/4/2013
	Product Type		RF
	Action Type		A
	Assigned To		J.BALIO
Cause	4038	Could Not Duplicate Concern	
Barrel	Description		22" 3006 SPRG
	Date Code		DQ
	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	

Bolt	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	SLUGGISH
Extractor	Condition	Slightly Worn; Functioning	
	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
Locking	Block Condition	---Select---	
	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	---Select---	
Overall	Exterior Condition	Slightly Worn; Functioning	
	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	---Select---	
Receiver	Condition	Slightly Worn; Functioning	
	Bulged	False	
Safety	Description		BOLT LOCK SAFETY
	Function	Like new; Functioning	
Sear	Lift	---Select---	L009
	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test		False	
Trigger	Condition	Slightly Worn; Functioning	DIRTY
	Pull	---Select---	5.5#
	Altered	False	
	Sub-Assembly	M700 Bolt Lock	

Service Request

Marlin Service

PO Box 1871

Madison, NC 27025-1871



Parts and Repairs: P:800-544-8892 F:336-548-7301

www.marlinfirearms.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service. PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

22"
DQ9/7
S.S.
1009

Service Request Number SR00058886		Serial Number / Description A6652084 Model R5793		Date of Request: 12/17/2012 Date Printed: 12/17/2012													
Customer: JOSE MONTOYA 511 SUMMERWINDS DR SE RIO RANCHO, NM 87124 US Email: JOECENTURY98@AOL.COM		Destination: Arms Services 14 Hoelder Ave Ilion, NY 13357 US Email:															
Your request for service on the item(s) will be evaluated by our repairman to determine if it is covered under our warranty policy. If it is your firearm will be repaired and returned. If not, you will be contacted with an estimate before work is performed.																	
Reason For Return M295 - EVALUATE AND REPAIR SAFETY INSP.																	
Service Request Section: DISCHARGES WHEN SAFETY IS DIS-ENGAGED																	
<table border="1"> <thead> <tr> <th>Parts And Service Details</th> <th>Description</th> <th>Qty Needed</th> <th>Warranty</th> <th>Price</th> <th>Disc Amount</th> </tr> </thead> <tbody> <tr> <td>Material</td> <td>Type</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>						Parts And Service Details	Description	Qty Needed	Warranty	Price	Disc Amount	Material	Type				
Parts And Service Details	Description	Qty Needed	Warranty	Price	Disc Amount												
Material	Type																
Serial Number: A6652084 Model: 700		<div style="text-align: center;"> <p>RE00294791</p> </div>															
		<div style="text-align: center;"> <p>RECEIVED</p> <p>JAN 07 2013</p> <p>BY:</p> </div>															
<p>could not dup. concern T.A. dirty. Rep. TPA, clean + rest and. BLP Ron 20 +</p>																	
THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the																	
				<p>Sub Total: .00 Est Sales Tax: .00 Grand Total: \$.00</p>													

U.S. Department of Justice
Bureau of Alcohol, Tobacco, Firearms and Explosives

Federal Firearms License
(18 U.S.C. Chapter 44)

COPI

In accordance with the provisions of Title I, Gun Control Act of 1968, and the regulations issued thereunder (27 CFR Part 478), you are licensed to engage in the business specified in this license, within the limitations of Chapter 44, Title 18, United States Code, and the regulations issued thereunder, until the expiration date shown. **THIS LICENSE IS NOT TRANSFERABLE UNDER 27 CFR 478.51. See "WARNINGS" and "NOTICES" on reverse.**

Direct ATF
Correspondence To
ATF - Chief, FFLC
244 Needy Road
Martinsburg, WV 25405-9431

License
Number
5-85-043-07-4D-01509

Chief, Federal Firearms Licensing Center (FFLC)

Expiration
Date
April 1, 2014

Name
RIO RANCHO ARCHERY & HUNTING INC

Premises Address (Changes? Notify the FFLC at least 30 days before the move.)

**1702 SOUTHERN BLVD
RIO RANCHO, NM 87124-**

Type of License

07-MANUFACTURER OF FIREARMS OTHER THAN DESTRUCTIVE DEVICES

Purchasing Certification Statement

The licensee named above shall use a copy of this license to assist a transferor of firearms to verify the identity and the licensed status of the licensee as provided by 27 CFR Part 478. **The signature on each copy must be an original signature.** A faxed, scanned or e-mailed copy of the license with a signature intended to be an original signature is acceptable. The signature must be that of the Federal Firearms Licensee (FFL) or a responsible person of the FFL. I certify that this is a true copy of a license issued to the licensee named above to engage in the business specified above under Type of License.

Mailing Address (Changes? Notify the FFLC of any changes.)

**RIO RANCHO ARCHERY & HUNTING INC
1702 SOUTHERN BLVD
RIO RANCHO, NM 87124-**

Licensee Responsible Person Signature

NASH Torres

Printed Name

CEO

Position Title

4/1/11

Date

*File copy only
Not to be used at
Gun Shows*

Previous Edition is Obsolete

RIO RANCHO ARCHERY & HUNTING INC, 1702 SOUTHERN BLVD, RIO RANCHO, NM 87124-01509, April 1, 2014, 07-MANUFACTURER OF FIREARMS OTHER THAN DESTRUCTIVE DEVICES

ATF Form 5310.11
Revised October 2011

Federal Firearms License (FFL) Customer Service Information

Federal Firearms Licensing Center (FFLC)
244 Needy Road
Martinsburg, WV 25405-9431

Toll-free Telephone Number: (866) 662-2750
Toll-free Fax Number: (866) 257-2749
E-mail: NLC@atf.gov

ATF Homepage: www.atf.gov
FFL eZ Check: www.atfonline.gov/fflcheck

Change of Address (27 CFR 478.52). Licensees may, during the term of their current license remove their business or activity to a new location at which they intend regularly to carry on such business or activity by filing an Application for an Amended Federal Firearms License, ATF Form 5300.38, in duplicate, not less than 30 days prior to such removal with the Chief, Federal Firearms Licensing Center. The application must be executed under the penalties of perjury and penalties imposed by 18 U.S.C. 924. The application shall be accompanied by the licensee's original license. The license will be valid for the remainder of the term of the original license. **(The Chief, FFLC, shall, if the applicant is not qualified, refer the application for amended license to the Director of Industry Operations for denial in accordance with § 478.71.)**

Right of Succession (27 CFR 478.56). (a) Certain persons other than the licensee may secure the right to carry on the same firearms or ammunition business at the same address shown on, and for the remainder of the term of, a current license. Such persons are: (1) The surviving spouse or child, or executor, administrator, or other legal representative of a deceased licensee; and (2) A receiver or trustee in bankruptcy, or an assignee for benefit of creditors. (b) In order to secure the right provided by this section, the person or persons continuing the business shall furnish the license for that business for endorsement of such succession to the Chief, FFLC, within 30 days from the date on which the successor begins to carry on the business.

(Continued on reverse side)

Cut Here X

Federal Firearms License (FFL) Information Card

License Name: **RIO RANCHO ARCHERY & HUNTING INC**

Business Name:

License Number: **5-85-043-07-4D-01509**

License Type: **07-MANUFACTURER OF FIREARMS OTHER THAN
DESTRUCTIVE DEVICES**

Expiration: **April 1, 2014**

Please Note: Not Valid for the Sale or Other Disposition of Firearms

FFL Newsletter - Electronic Version Available

Sign-Up Today!

FFLs interested in receiving the electronic version of the FFL Newsletter, along with occasional additional information, should submit name, FFL number, and e-mail address to: FFLNewsletter@atf.gov.

The electronic FFL Newsletter will enable ATF to communicate information to licensees on a periodic basis.





