Remington Arms Co., Inc. **Product Service** Legal Case #:8747

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Lit Obsolete 3/27/2013 3/28/2013 3/28/2013 306184

Customer Information

State Zip Age Business First Name Last Name Street City Contact Type W 972-932-9747 3001 S. Washington St. Kaufman TX 75142 Incident Johnny Perry C 214-796-6619

Incident Information

Claims Codes Repair Est. **Medical Status Medical Treatment**

ΡI

PD Cause:4038 Could Not Duplicate Concern

S FBC C

Concern: 1008 Fired on Bolt Closing

Unknown

SR# 46462 - Service Request Section: "safety modification program". Customer wrote on our repair form: "Close bolt and gun fired disassemble trigger and clean and blow out with air hose, oil & reinstall seem to fix problem". df

Firearm Information

Mfg.

Type

Model/Ga. 700/264 WIN MA SKU

Serial Bbl. DOM 64807 CK 4/1/1963

CF/BA Remington Date Purchased Where Purchased

Accessories

n/a **Original Owner**

SCOPE BASE, BOTTOM HALF OF RINGS

Y

CONCERN: FBC

Ammunition Information - None Defined Other Products Information - None Defined Settlement

Remington/700/CF/BA

Settlement

Release of Claims

Release Date

Reimbursement

Reim. Settlement Date APV Cash Date APV

Per Ilion - Quote to repair under BLM

> Repair/Replacement Repair/Replacement Cost Date

> > \$29

4/1/13: Per Ilion - Could not duplicate concern. Replace TA, clean & test under BLM - quote. A CSR called customer & received apprv. & payment on 3/28/13. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment	
	Examiner		B.TRAVIS	
	Exam Date		3/28/2013	
Examination	Product Type		RF	
	Action Type		A	
	Assigned To		S.NICHOLS	

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=8747&Type=Case

4/1/2013

Cause	4038	Could Not Duplicate Concern	
	Description		24" 264 WIN MAG
	Date Code]	CK
	Bore Plugged	False	
Barrel	Bulged	False	
Dallei	Fired	False	
	Fired while Obstructed		
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Worn; Functioning	FINISH REMOVED FROM BBL
Overall	Stock Condition	Slightly Worn; Functioning	REM SYN STK
	Fore End Condition	Select	
Receiver	Condition	Worn; Functioning	LITE RUST, FINISH WEAR
Receiver	Bulged	False]
Safety	Description]	BOLT LOCK SAFETY
Salety	Function	Slightly Worn; Functioning	
	Lift	Select	.008
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	T CSIS	False	
Trigger	Condition	Slightly Worn; Functioning	
	Puli	Select	4#
1115561	Altered	False	FACTORY SEALANT MISSING
	Sub-Assembly	Other Remington	
Non-Remington Components	Description		SCOPE BASE,BOTTOM HALF OF RINGS

Service Request

Remington Service

Madison, NC 27025-0700

Parts and Repairs: P:800-243-9700/F:336-548-7801

www.Remington.com

This document is a summary of your request for service. Please review the document for accuracy and to insure the services you are requesting are noted. This information will serve as a guideline for our Service Department to address your specific concerns and provide you with accurate and complete service PLEASE RETAIN THIS COPY FOR YOUR RECORDS.

24" C124/67

Service Request Number	Serial Number / Description	~ 7017		Date of	Request:	02/27/2013		
SR00046462	64807	: 8 /IL		Date	Printed:	02/27/2013		
	Model	, ,						
Customer:		I	estination:					
JOHNNY PERRY			Arms Services					
JUSTICE OF THE PEA			14 Hoefler Ave					
300 SOUTH WASH		Ilion, NY 13357 US						
KAUFMAN, TX 7514	12 US							
Email: catfishperry@gm	zil.com		Email:					
-Your request for service on t	he item(s) will be evaluated by our r	epairman to četermine if it is co	vered under our warranty	policy. I	f it is your fu	rearm will be		
repaired and returned. If not	, you will be contacted with an estin	nate before work is performed.						
		•						
	•		•					
	•							
M			NUT ASSESSED TO SEE STATE OF THE SECOND	Na ville i	. 774 -1 875- 11	D		
				En In		SE WILLIAM		
Reason For Return		The second second	5万年	是一部				
M240 - BOLT LOCK SA	FELT MODIFICATION							
		•	•					
Constant D'abanda Constant	The state of the s	1470 (ACE) 1270 中区 (AMIC	NATIONAL PROPERTY OF THE STATE		18 m 1 758 r 250	esta Tienamente april for y		
Service Request Section		CHI SULLENG MERCHANIZANE	are a construction of the second	語為	4.5	the second of the second of		
safety modification program					*			
		وثي						
			•					
			•					
Parts And Service Details		心"的一句"理解来必要"	2000年2000年200	特別。特		SALES MANAGEMENT		
Material Type	Description	Qty Neede	Warranty		Price	Disc Amount		
		17 ee a e	;u		•			



could not dy, concern.

step. TPA, CLEHN+ TOST PRECETVET

BUP Con 20+ APR- 2013

THIS IS NOT AN INVOICE. This is a pre-estimate to repair, recondition, or replace the

Sub Total: .00
Est Sales Tax: .00

Grand Total: \$.00

Model Number: 700	Number: 700 Serial Number: 64807		
Are you the original owner	?: FYES F	NO	
Name: Johnny Perry	Date of Purchase:		
Address (no PO	Boxes):		
10780 CR 15	7		
City: KAUFMAN	State: 7x	Zip: 75142	
Phone (Daytime): 214 796 6619	Fax: 972 962 2653		
E-mail Address:(if e-mail address is pro		of receipt and	
shipment wi	ll be ·		
E-mail Addr □ I would like to receive future e-mail		Remington.	
Please describe your problem a			
Close bolt And disassemble trisser blow out with Air reinstall seem to	hose, or	in ml	
Ammunition Info	rmation:		
Manufacturer: Reming tow	Type: 244 W	Vin MAZ	
Other (i.e. bullet weight/ powder):			
Handload Infor	mation:		
Powder Used:	Powder Weight:		
Case/Hull Used:	Primer Used:		
Bullet Type/Shot Size:	Reloader Used:		
Firearms Care (Cleaning a	and Lubrication)	:	

General Repair Form Page 2 of 3

Brand of cleaning solution used:
How often do you clean the bore? (Months or Number of rounds)
How often do you clean the action? (Months or Number of rounds)
How often do you clean the trigger assembly? (Months or Number of rounds)
Brand of lubricant used: Reming for
How often do you lubricate the bore? (Months or Number of rounds) When Cleaning
How often do you lubricate the action? (Months or Number of rounds) When Cleaning
How often do you lubricate the trigger assembly? (Months or Number of rounds) When Chaning
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?
When was the last time that your firearm was serviced by a Remington authorized repairman/gunsmith?)
What were the services
performed?)
Ship your INSURED firearm by either UPS or Parcel Post to:
Please select a state from above to view the address of the Premier Field Service Center in your area.
WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM. THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL NUMBER OF YOUR FIREARM.
Record the serial number of your firearm before sending it. Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably, ship in a firearm box. (Note: Original boxes may not be returned.) Remove all accessories from your firearm to prevent loss or damage.

Johnny Perry Cell # 214.796-6619 Work# 972 932 9747

Return Address

Justice of the Peace 3001 South Washington St. XAUfman, TX. 75142







