

|                       |                       |                       |                  |
|-----------------------|-----------------------|-----------------------|------------------|
| File Number:          | 9837                  | Arms Service Number:  | 6720389          |
| Last Name:            | BURDICK               | First Name:           | WILLIAM          |
| Street:               | 660 SPRING HILL DR    | City:                 | ALBANY           |
| State:                | OR                    | Zip:                  | 97321            |
| Home Ph:              |                       | Home Ph:              | 541 926 3696     |
| Work Ph:              |                       | Product Type:         | F A T O          |
| Type Concern:         | S FI PD P S C         | Concern Code:         | 1007             |
| Concern:              | FIRED ON SAFE RELEASE |                       |                  |
| Case Code:            | 4039                  | Cause:                | NO FAULT FOUND   |
| Assigned To:          | KAST                  | Classification:       | UNC UNL UNC UNCL |
| Settlement Detail:    | REPAIR SPCL PRICE     |                       |                  |
| Date Opened Rem:      | 11/25/97              | Date Opened by PR:    | 12/3/97          |
| Date of Incident:     |                       | Date Closed:          | 12/3/97          |
| Date to Analyze:      |                       | Date from Analysis:   |                  |
| Model:                | 700                   | Serial:               | AG826509         |
| RAMAG:                | 700                   | Legalism:             |                  |
| Quantity:             |                       | Comments:             |                  |
|                       |                       | Settlement Amount:    | 50.00            |
|                       |                       | Caliber:              | 270              |
|                       |                       | Bullet Weight:        |                  |
|                       |                       | Manufacturer:         | REM              |
|                       |                       | Date Mfgd:            | 11/1/79          |
|                       |                       | Obsolete:             |                  |
| Time of Modification: | 1:49:55 PM            | Date of Modification: | 12/3/97          |

## RECEIVING AND ESTIMATING REPORT

COMMENTS

Product  
ServiceORDER  
R 97-20389

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/24/97

11/25/97

RV 11-79

A6826509

700 270

BDL/LH

ACCESSORIES

L/SIGHTS

W/STUDS

FROM:

SHIP TO:

BURDICK, WILLIAM  
950 SPRING HILL DR  
ALBANY

OR 97321

BURDICK, WILLIAM  
950 SPRING HILL DR  
ALBANYOR  
97321

CUST NO: 177894 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

12-3-97

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

38.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

Total

CYCLE

A1

B1

TRIGGER GROUP

B3

SLT ASSY.

B3

BARREL ASSY.

D1

EC. ASSY.

D2

FOOD

D3

ETAL

IN FAULT

The only way that the gun could be made to fire as read. Was with the safe off and the trig. pulled.

Customer may have inadvertently contacted trig when releasing safe.

Exchange trig. Assy. at a spec. price strictly as a gesture of good will.

RTS

COMMENTS

Trig pull 4 1/2 LBS as read

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6025 REV. 7-97

PS 34471

WILLIAM BURDICK  
950 SPRING HILL DR.  
ALBANY, OR. 97321

541-926-3896

REMINGTON MODEL 700 LH SER. NO. A6826509

To whom it may concern

The reason I am returning this rifle to you is because;

When the rifle is loaded and the safety is on, the rifle has discharged upon moving the safety to fire.

( '96 )  
This rifle did this last year during hunting season. I took it to a good reputable gunsmith who thought he had fixed the problem. This year I took this rifle hunting again and on the first morning the problem happened again. Luckily I was hunting with the same guys as last year. After much ribbing I had to use my backup rifle. If I bring this rifle hunting again they have told me that I would be hunting alone. I really like this rifle and have used it alot, but I doubt very much if I can trust to use it again.

Bill Burdick