

File Number: 8929		Arms Service number: 9703780	
Last Name: ROUBIQUE		First Name: JED	
Street: PO BOX 284		City: FORDOCHE	
State: LA	Zip: 70732	Home Ph: 504-389-9377	
Work Ph: 800-329-8281	Product Type: F F A T		
Type Concern: S	PI PD P S	Concern Code: 1005	
Concern: UNEXPLAINED DISCHARGE - SAFE ON			
Cause Code: 4006	Cause: ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To: SUPRY	Classification: UNJ UNJ UNC UND J		
Settlement Detail: REPLACE FC AT SPECIAL PRICE	Settlement Amount: \$25.00		
Date Opened Rem: 2/11/97	Date Opened by P/S: 1/7/97		Caliber: 280
Date of Incident: 12/15/96	Date Closed: 2/11/97		Bullet Weight:
Date to Analysis:	Date from Analysis:		Manufacturer: REM
Model: 700	Serial: C6281022	Date Code: OI	Date Mfgd: 7/1/88
RAMAC: 700	Litigation: <input type="checkbox"/>	PreLitigation: <input type="checkbox"/>	Obsolete: <input type="checkbox"/>
Custody:	Comments: trigger screws adjusted to an unsafe condition - less than one pound pull - also sticky residue built up in fire control		
Time of Modification: 8:54:35 AM		Date of Modification: 1/9/97	

File Number:	8929	Arms Service number:	
Last Name:	ROUBIQUE	First Name:	JED
Street:	519 AVENUE A	City:	PORT ALLEN
State:	LA	Zip:	70767
Home Ph:	504-389-9377		
Work Ph:	800-329-8281	Product Type:	F A T
Type Concern:	S	Concern Code:	1005
Concern:	UNEXPLAINED DISCHARGE - SAFE ON		
Cause Code:	4040	Cause:	OTHER - UNEXAMINED
Assigned To:	SUPRY	Classification:	UND UNJ UNC UND J
Settlement Detail:		Settlement Amount:	\$0.00
Date Opened Rem:	1/7/97	Date Opened by P/S:	1/7/97
Date of Incident:	12/15/96	Caliber:	280
Date to Analysis:		Bullet Weight:	
Date from Analysis:		Manufacturer:	REM
Model:	700	Date Mfgd:	
Serial:			
RAMAC:	700	Litigation:	<input type="checkbox"/>
Custody:		PreLitigation:	<input type="checkbox"/>
Comments:	is sending firearm to my attention - he called to ask for us to send a box		
Time of Modification:	8:54:35 AM	Date of Modification:	1/9/97

1/24/97 - shipped box under APO # 883

## RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER  
R 97-03780

INITIAL CUSTOMER ORDER NO.

JJM

ATTN FRED SUPRY

DATE RECEIVED

02/04/97

DATE OPENED

02/11/97

DATE CODE

OI 7-88

SERIAL NUMBER

C6281022

NEW SERIAL NUMBER

MODEL AND GRADE

700 280

RS

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

ROUBIQUE, JED L  
P O BOX 284  
FORDOCHE

LA 70732

SHIP TO:

ROUBIQUE, JED L  
P O BOX 284  
FORDOCHELA  
70732

CUST NO: 161868 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PRGM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED*Accidental discharge safe on*

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

METAL

C2

MAIN FAULT

*Trigger Adjustments SCREWS have been adjusted to  
an unsafe condition - The fire control contains  
sticky residue - LESS THAN 1 POUND TRIGGER PULL.  
- Could NOT DUPLICATE CUSTOMER CONCERN*

PARTS

COMMENTS

*Replace fire control at  
special price, 1/2 normal rate  
FLS 2/11/97*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

R06925 REV. 11/96

February 02, 1997

Jed L. Roubique  
P.O. Box 284  
Fordoche, La. 70732  
(504) 637-2619  
(504) 389-9377

Remington Arms Company Arms Service  
Mr. Fred Supry  
14 Hoefler Avenue  
Ilion, NY 13357


Dear Mr. Supry,

I am writing in regard to my Remington Model 700. I was sitting on my tree stand one morning and my .280 caliber Model 700 just went off for no reason. The gun was on safety and nothing was around the trigger. Lucky the gun discharged in a safe direction and no one was injured.

I loaded the gun around 6:30 am that morning and it discharged around 10:00 am that morning for no reason. It was a clear day and the temperature was around 65-70 degrees.

After the gun went off I tried to bolt my gun but the bolt would not move. The safety was stuck on safety. I could not get the safety to go into the fire position. I had to squeeze the trigger and I heard a click. It sounded like the firing pin passed the trigger up. After, the clicking noise from pulling the trigger everything worked fine. However, I do not trust my Remington gun any more.

Thanks,



Jed L. Roubique  
A Concerned Remington Consumer