

File Number:	9649		Arms Service number:	9713689	
Last Name:	T&M SHOOTING SPORTS			First Name:	
Street:	RT 6 BOX 184			City:	LITTLE FALLS
State:	NJ	Zip:	56345	Home Ph:	
Work Ph:	320 832 9204	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S C	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	KAST	Classification:	UNJ	UNJ UNC UND J	
Settlement Detail:	REPAIR SPCL PRICE			Settlement Amount:	\$0.00
Date Opened Rem:	7/31/97	Date Opened by P/S:	10/15/97	Caliber:	30-06
Date of Incident:		Date Closed:	10/15/97	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	C6344565BJ	Date Code:	1/89
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Custody:		Obsolete:	☐		
Comments:	inside of trip, gummed up				
Time of Modification:	11:33:34 AM		Date of Modification:	10/15/97	

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER
R 97-13689

INITIAL JJM	CUSTOMER ORDER NO.					
DATE RECEIVED 07/29/97	DATE OPENED 07/31/97	DATE CODE BJ 1-89	SERIAL NUMBER C6344565	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL
ACCESSORIES W/STUDS		SCOPE BASE				

FROM:

T & M SHOOTING SPORTS
RT 6 BOX 184
LITTLE FALLS MN 56345

SHIP TO:

T & M SHOOTING SPORTS
RT 6 BOX 184
LITTLE FALLS MN 56345

CUST NO: 014860 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED 10-19	VIA UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED			REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL 43.00		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.						F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

1984 Trigger is sluggish and slow to return as rec'd. Sear sticks down in housing as rec'd. INSIDE OF TRIGGER Housing, sear and trigger are gummed up with old lacquer like substance causing components to stick.

Exchange Trig Assy at a special price strictly as a gesture of good will.

PARTS

COMMENTS

Trig. pull 4 3/4 lbs as rec'd

Trig. Assy.

Bolt stop stuck as rec'd.

See owners manual for proper care and maintenance

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN ☒	TEST ☒	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 6/96

PS 34900

SHOOTING SPORTS

Route 6, Box 184
Little Falls, MN 56345
320-632-3204



EARL KEN KNEELAND

TYRONE UMLAUF

7-16-97

Remington ARMS CO.
ARM'S SERVICE
14 HOEFLER AV.
ILION NY 13357

ATTN: REPAIR

ENCLOSED PLEASE FIND AN Remington
MOD 700 BDL #C6344565 in The
0-06 CAL.

OUR CUSTOMER'S COMPLAINT IS THE
S RIFLE HAS Discharged When
TAKEIN OF SAFETY.

Please Repair UNDER WARRANTY.

you have any Questions
Please CALL.

"EARL"