

File Number: 9581 Arms Service number: 9713060
Last Name: VALLEY GUNSMITHING - JOHN A FO First Name:
Street: 619 SECOND STREET City: WEBSTER CITY
State: IA Zip: 50595 Home Ph:
Work Ph: 515-832-5102 Product Type: F F A T
Type Concern: S PI PD P S Concern Code: 1008
Concern: FIRED ON BOLT CLOSING
Cause Code: 4040 Cause: OTHER - UNSPECIFIED OR UNDETERMINED
Assigned To: SANITA Classification: UND UNJ UNC UND J
Settlement Detail: REPLACE FC N/C Settlement Amount: \$50.00
Date Opened Rem: 7/18/97 Date Opened by P/S: 7/19/97 Caliber: 270
Date of Incident: 8/1/97 Date Closed: 9/23/97 Bullet Weight:
Date to Analysis: Date from Analysis: Manufacturer: REM
Model: 700 Serial: C6829508 Date Code: DN Date Mfgd: 9/1/93
RAMAC: 700 Litigation: PreLitigation: Obsolete:
Custody: Comments: Replace complete trigger assembly n/c
Time of Modification: 9:30:31 AM Date of Modification: 9/23/97

RECEIVING AND ESTIMATING REPORT

COMMENT'S

Product Service

ORDER

R 97-13060

INITIAL

CUSTOMER ORDER NO.

JJM

8975

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

07/16/97

07/18/97

DN 9-93

C6829508

700 270

BDL

ACCESSORIES

W/STUDS

FROM:

SHIP TO:

VALLEY GUNSMITHING
JOHN A FOSTER
619 SECOND ST
WEBSTER CITY

IA 50595

VALLEY GUNSMITHING
JOHN A FOSTER
619 SECOND ST
WEBSTER CITY

IA 50595

CUST NO: 001722 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

2016501

WRITE



FROM DATE

ESTIMATED

VIA

9/19/97 UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

F5

METAL

MAIN FAULT

*Got my stuff
Safety was not go on when loaded
Safety fails when bolt is closed**Club for best strong hand, more than normal force
was required to move the safety bar*

PARTS

COMMENTS

#26345

*Replace the damaged trigger
bar.**1008
4040**Repair at no charge*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 11/96

PS 34914

ORDE

JOHN A. FOSTER
VALLEY GUNSMITHING
619 Second Street
Webster City, Iowa 50595
(515) 832-5102

OR		REG. NO.	DATE REQUIRED	HOW SHIP	TERMS	DATE	
Leibold				UPS			
QUANTITY		PLEASE SUPPLY ITEMS LISTED BELOW				PRICE	UN
ORDERED	RECEIVED						
		Rem. M700BDL, 2 - #C6829508					
		Customer stated he was target shooting when gun malfunctioned:					
		(1) Bolt lift very stiff					
		(2) Safety will not go on when cocked. If you do get safety on, striker falls when safety moved to off.					
		(3) Striker usually falls when bolt is closed, but trigger sears remain engaged					
		Please inspect & correct.					

PLEASE SEND COPIES OF YOUR INVOICE WITH ORIGINAL BILL OF LADING

PURCHASING AGENT

ORIGINAL