



File Edit View Records Window Help



Customer Service Data Entry			
FIND			
File Number: 9467		Arms Service number: 370903	
Last Name: WALKER		First Name: COYLE	
Street: 832 W UNION		City: JACKSBORO	
State: TX	Zip: 76458	Home Ph:	
Work Ph:	Product Type: F	F A T O	
Type Concern: S	PI PD P S C	Concern Code: 1025	
Concern: UNEXPLAINED DISCHARGE AND MENTION SAFETY POSITION			
Cause Code: 4013	Cause: BROKEN PARTS CONNECTOR BROKEN DUE TO ALTERATION		
Assigned To: KAST	Classification: UNJ	UNJ UNC UND J	
Settlement Detail: REPAIR SPCL PRICE	Settlement Amount:		\$0.00
Date Opened Rem: 5/2/97	Date Opened by P/S:	7/21/97	Caliber: 222
Date of Incident:	Date Closed: 7/21/97	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer: REM	
Model: 700	Serial: B6292378	Date Code: NON	Date Mfgd:
RAMAC: 700	Litigation: ☐	PreLitigation: ☐	Obsolete: ☐
Custody:	Comments: OVERTRAVEL SCREW BACKED OUT AS RECD AND POUNDS PULL WAS ALTERED		
Time of Modification:	9:43:21 AM	Date of Modification:	7/21/97

Form View

FLTR

CAPS NUM

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product Service

ORDER

97-09038

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

04/29/97

05/02/97

B6292378

700 222

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

WALKER, DOYLE
832 W UNION
JACKSBORO

TX 76458

SHIP TO:

WALKER, DOYLE
832 W UNION
JACKSBORO

TX
76458

CUST NO: 166472 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

7-18-97

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

42.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

WOOD

C1

METAL

C2

MAIN FAULT

*Trigger connector is broken
and gun will accidentally discharge*

Trigger improperly adjusted outside of the factory - not recommended. Exchange trigger assy at a special price strictly as a gesture of good will.

PARTS

COMMENTS

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 11/96

DATE 4-19-97

SUBJECT

Remington BDL 700.

222

SN B6292378

Remington Service Dept
14 Hoessler Ave
Illion, NY 13357

Enclosed Please find a Remington 700BDL
222 SN B629238, the Trigger Connector is
Broke and the gun will accidentally discharge.

Please look into this problem.

Thank you,

DOYLE WALKER

832 W. Union

JACKSBORO, 276458

☐ PLEASE REPLY

☒ NO REPLY NECESSARY

SIGNED

Doyle Walker