

File Number:	9796	Arms Service number:	9719688
Last Name:	WHITE	First Name:	DAVID
Street:	6411 HWY U	City:	HILLSBORO
State:	MO	Zip:	63050
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F A T
Concern:	FIRED ON BOLT CLOSING	Concern Code:	1008
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SANTA	Classification:	UNJ
Settlement Detail:	REPAIR AT SPEC. PRICE, CHANGE TRIG ASSE	Settlement Amount:	\$40.00
Date Opened Rem:	11/14/97	Date Opened by P.S.:	11/20/97
Date of Incident:		Date Closed:	11/24/97
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	A6418368
RAMAC:	700	Date Code:	IOP
Custody:		Date Mfgd:	10/1/77
Litigation:	☐	PreLitigation:	☐
Obsolete:	☐	Comments:	
Time of Modification:	8:32:30 AM	Date of Modification:	11/24/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 97-19688

INITIAL CUSTOMER ORDER NO.

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/13/97

11/14/97

EO 10-77

A6418368

700 30-06

BDL

ACCESSORIES

W/STUDS

L/SIGHTS

FROM:

WHITE, DAVID
6411 HWY Y
HILLSBORO

MO 63050

SHIP TO:

WHITE, DAVID
6411 HWY Y
HILLSBOROMO
63050

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

CUST NO: 177095 C.O.D.

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE 28.00

EXCISE

TAX

INSURANCE

UPS 8.00

PARCEL POST

TOTAL 36.00

Prod Serv.

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

E3

F3

REC. ASSY.

B5

E4

F4

WOOD

B6

E5

F5

METAL

B7

E6

F6

MAIN FAULT

Left mfg 1977 upon receipt we could not duplicate the reported concern. However, examination did reveal that the bolt stop release and trigger were wearing sluggish from being covered with a sticky substance. The trigger housing and the action are also covered with this substance. The rifle has been properly maintained.

PARTS

COMMENTS

26345

1008

4015

Replace the compact trigger assembly & clean the action at 1/2 the normal repair cost, as per your price.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

go ahead

OFFICE COPY

RD6925 REV. 7-97

INFORMAL MEMO

DATE 11-3-97

TO MR. or MS.

700
MY Remington 7400 30.06 Rifle
Model Number A6418368, is missfiring.
Sometimes it will fire when I
unlock the bolt to unload it, and
sometimes it will fire when I
push the safety off.

I spoke to the people in
the office at Remington and they
told me to send the rifle to
this department for repair. sure
hope you can help.

PLEASE RETURN TO:

David White

6411 Hwy. Y

Hillsboro, Missouri 63050

SIGNED _____

AVOID VERBAL ORDERS

MAC 31 (REV 1 MAR 88)