

Serial Number: E6433749

Model ID: 700



RE00000237

Could not duplicate Customer Concerno of FSR.

Exchange TPA as gestive of goodwill We Check rifle out completely

Charge 230145

FCS 12/13/99

REN	MINGTON REPA	IR INSTRUCTIONS
Name:	ROUNIE CARTER	Model: 700 ADL .308 WIN.
Mailing Address:	POBOX 691	Serial #: E 6 4 3 3 7 4 9
Telephone:	DAYTON TX 77535 Day 409 258 3776 Evening	Date of Purchase: SPRING 1999 (If available, please attach a copy of the proof of purchase.)
CLOSE	ibe the problem you are having with your 2 bolt with bullet TR WAS NOT ON TO	,
	BOSWIN. Brand Reminston 150gy, Shot Size:	or Handload Specifications:
please provid	le copies of your repair paperwork.	Remington or a Remington Authorized Repair Center ia to determine if the repair will be charged to
	Date of Purchase Type of Repair	
provide credi also expedite	t card authorization now. An estimate will repairs over \$75 by setting a pre-authorized	rned C.O.D To avoid C.O.D processing, you may be mailed for repairs over \$75. If you wish, you can amount that can be billed to your credit card.
You may rep	pair my firearm and bill my credit card fo	or charges up to \$
Credit Card (American Ex	Number:xpress, Discover, MasterCard, or Visa)	Expiration Date:
Signature: _		
Properly packs Parts Departme	erial number—it will help reference your repair age your unloaded firearm. Do not ship in a harent: 800-243-9700, 9 a.m 5p.m., EST. ye/loaded ammunition with your firearm.	d case. If you would like to order a box, please call our

Remove all accessories.

