

File Number:	11725		Arms Service number:	9915115	
Last Name:	DORNS GUN SERVICE		First Name:		
Street:	3747 NAPIER AVE		City:	MACON	
State:	GA	Zip:	31204	Home Ph:	
Work Ph:			Product Type:	F A T	
Type Concern:	S	Ph PD P S	Concern Code:	1020	
Concern:	FIRED ON BOLT OPENING				
Cause Code:	4040	Cause:	OTHER UNSPECIFIED OR UNDETERMINED		
Assigned To:	CANITA	Classification:	UNC	UNJ UNC UND	
Settlement Detail:	REPLACE TRIG ASSEM. GOODWILL			Settlement Amount:	\$0.00
Date Opened Rem:	8/4/99	Date Opened by P/S:	8/10/99	Caliber:	7MM-06
Date of Incident:		Date Closed:	8/17/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	D6275620	Date Code:	BT
RAMAC:	700	Litigation:	☐	Date Mfgd:	1/1/99
Custody:		PreLitigation:	☐	Obsolete:	☐
Comments:					
Time of Modification:	8:47:03 AM		Date of Modification:	8/17/99	

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
Service

ORDER
R 99-15115

INITIAL
PSP

CUSTOMER ORDER NO.

DATE RECEIVED
08/02/99

DATE OPENED
08/04/99

DATE CODE
BT 1/99

SERIAL NUMBER
D6275620

NEW SERIAL NUMBER

MODEL AND GRADE
700 7MM-08

MTM/DM

ACCESSORIES

W/STUDS

FROM:

DORNS GUN SERVICE
3747 NAPIER AVENUE
MACON

GA 31204

SHIP TO:

DORNS GUN SERVICE
3747 NAPIER AVENUE
MACON

GA
31204

CUST NO: 001078 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER WIC

830145

WRITE

☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN/CONDITION

- ☒ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

METAL

MAIN FAULT

Upon receipt we could not duplicate the reported concern, the complete trigger housing assembly was disassembled & examined. We found no components out of specification.

PARTS

COMMENTS

1020

4040

Repair the complete trigger housing assembly to help restore full on safety.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

DORN'S GUN SERVICE
E.I.G.S. (EXCELLENCE IN GUN SERVICE)

WARRANTY SERVICE FOR
BROWNING, COLT, REMINGTON, WINCHESTER (USRA)
AUTHORIZED FRANCHISE INSTALLATION CENTER FOR K&F RECON. ARRESTORS
4388 MERCER UNIV. DR.
MACON GA 31206
PHONE (912) 471-0304 FAX * (912) 474-7994

DATE 7-22-99

TO
REMINGTON ARMS SERVICE DEPT.
14 HOEFLER AVE.
ILLION, N Y 13357

Mountain

THIS MODEL 700 SERIAL #D6275620 IS RETURNED FOR YOUR REPAIR
DUE TO THE RESTRICTED PARTS INVOLVED

TRIGGER PROBLEM
THE NATURE OF THE COMPLAINT
INFO ENCLOSED
PLEASE RETURN WHEN COMPLETED TO

SPORTSMAN WHSE

ATTN: CURTIS

3825 SHACKELFORD RD

770-931-1550

DULUTH GA 30136

OUR SHOP

NO

THANK YOU

Bill

BILL DORN

DEFECTIVE GUN
RETURN TO MANUFACTURER

SKU #

Manufacturer: Remington Serial Number: 06275620

Model: XO MTR RIF Log #: DM

Action, Color, Caliber: Bolt W/B 7MM08 Date: 7/21/99

Return to:

Send repaired gun to:
ATTN: Quater
SPORTSMAN'S WHSE
3825 SHACKELFORD ROAD
DULUTH, GA 30136
(770) 931-1550

Service / Repair
Center

Why is gun defective?

When Safety is on Fire Position The Hammer Dropped
When The Bolt Was Licked + Return Twice in about 10-15 Trys
Associate's Signature and Date: Has Not Done it in about 20 more Trys
Adam Has NOT Been Fired

C. J. Sloan

RPS CUST

Please send
all information on
Repair to tell
Customer