

File Number:	11448	Arms Service number:	9908494
Last Name:	NELSON	First Name:	MACRAY
Street:	781 W 1050 N	City:	CEDAR CITY
State:	UT	Zip:	84720
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F
Concern Code:	1008		
Concern:	FIRED ON BOLT CLOSING		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANTA	Classification:	UNJ
Settlement Detail:	SEND EST TO REPAIR AT SPEC PRICE		Settlement Amount:
Date Opened Rem:	03/30/1999	Date Opened by P/S:	03/30/1999
Date of Incident:		Date Closed:	03/31/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	6276819
RAMAC:	700	Date Code:	DS
Litigation:	<input type="checkbox"/>	PreLitigation:	<input type="checkbox"/>
Custody:		Obsolete:	<input type="checkbox"/>
Comments:	incident shell is a reload, nickel primer		
Time of Modification:	10:03:19 AM	Date of Modification:	03/31/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 99-08494

INITIAL CUSTOMER ORDER NO.

PS

W/I SPENT CASE
L/REAR SIGHT

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

03/26/99

03/30/99

DS 9-69

6276819

700 30-06

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

NELSON, MACRAY
781 W 1050 NORTH
CEDAR CITY

UT 84720

NELSON, MACRAY
781 W 1050 NORTH
CEDAR CITYUT
84720

CUST NO: 208031 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

E3

F3

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

my 1969 Gun went off
One fired case not it has a misfired primer indicating this is a misfired cartridge. Found no fault with bolt group. Inside the trigger housing group we found dent. The trigger adj. screw has been re-set.

COMMENTS

Send out to replace trigger group & chamber at Spec Plus

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

Remington Arms Company, Inc. Repair Instructions

Print and complete this form and mail it along with your firearm.

Prior to shipping your firearm, contact the Repair Center for services provided and estimated repair time.

Name: MacRay Nelson Model: 700
Address: 781 West 1050 North Serial #: 6276819
City: Cedar City Date of Purchase: I received as a gift
State: Utah Zip: 84720 (if available, please attach a copy of the proof of purchase.)
Country: USA
Telephone: (Day) (435) 590-1981 Internet Request
(Night) (435) 865-9162
435

Please describe the problem you are having with your firearm: _____

I was sighting in the rifle, I fired two (2) rounds through it. when I was shucking the third (3rd) round into the chamber the gun went off. The bolt was about 2/3 closed. Enclosed is the empty Cartridge of which went off

Optional Information

Ammo Type: _____ Brand: _____

or Handload Specification _____ Bullet Weight: _____ Shot Size: _____

Reminders:

Record your serial number - it will help you reference your repair.
Properly package your unloaded firearm. Do not ship in a hard case.
If you would like to order a box, please call our Parts Department:
800-243-9700, 9am-5pm, EST, Monday-Friday.
Do not send live/loaded ammunition with your firearm.
Remove all accessories.

Back to Obtaining Repair Service

©1998 Remington Arms Company, Inc.

I could not get the mount (scope) off of the barrel. Is there any possible way someone can take them off and return them to me.

thank you

Sincerely, MacRay Nelson

www.remington.com/consumer/repairsvc/repairform.htm