

File Number:	11672		Arms Service number:	9913940	
Last Name:	PIPER		First Name:	WAYNE A JR	
Street:	PO BOX 128		City:	HYANNIS	
State:	NE	Zip:	69350	Home Ph:	308-458-2380
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SANITA	Classification:	UND	UNJ UNC UND	
Settlement Detail:	NEW FC AT N/C		Settlement Amount:	\$40.00	
Date Opened Rem:	7/12/99	Date Opened by P/S:	7/12/99	Caliber:	17
Date of Incident:		Date Closed:	7/13/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	E6381152	Date Code:	ER
Date Mfgd:	10/1/97				
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Obsolete:	☐				
Custody:		Comments:	Trigger assembly rec'd in plastic bag in pieces. All three adjustment screws have been tampered with. Trigger connector broken - unable to determine when connector broke. Replace trigger assembly n/c as gesture of goodwill.		
Time of Modification:	2:29:53 PM		Date of Modification:	7/13/99	

RECEIVING AND ESTIMATING REPORT			COMMENTS ENHANCED		ORDER R99-13940	
INITIAL PS	CUSTOMER ORDER NO.					
DATE RECEIVED 07/12/99	DATE OPENED 07/12/99	DATE CODE ER 10-97	SERIAL NUMBER E6381152	NEW SERIAL NUMBER	MODEL AND GRADE 700 17 REM	BDL
ACCESSORIES W/STUDS		L/SIGHTS				

FROM:	SHIP TO:
PIPER, WAYNE A JR P O BOX 128 HYANNIS NE 69350	PIPER, WAYNE A JR P.O BOX 128 HYANNIS NE 69350

CUST NO: 211822 C.O.D	
ACCOUNT NUMBER 230145	ACCOUNT NUMBER N/C
WRITE ☐	PROM. DATE
	ESTIMATED
	VIA UPS
GUN CONDITION	REPAIR CHARGE
☒ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
☐ MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D4	E3	F3
REC. ASSY.		B5				
WOOD			C1	D3	E5	F5
METAL						

MAIN FAULT	
<i>Trigger group needs in place; has in place. All the</i> <i>adjustment screws have been tampered with.</i> <i>Trigger group is broken - unable to determine when connected</i> <i>to the</i>	
PARTS	COMMENTS
	<i>Replace complete trigger group</i> <i>at no charge as gesture of</i> <i>goodwill</i>
1007	
4000	
REPAIRMAN	PROOF
CLEAN ☒	TEST ☒
TARGET	PATTERN
GALLERY TESTER	DATE
DATE	DATE
DATE	DATE

OFFICE COPY

RD6925 REV. 7/97

Aliant
Cellular

CUSTOMER SERVICE

Omaha: 402-758-2400
Lincoln: 402-436-5050
Greater NE: 800-578-1054

The gun has been shot
about 75 times. All factory
loads. A part inside of the
trigger broke it would not
set the trigger after a shell
was put in the chamber unless
the safety was on. When the
safety was flipped to fire,
it would go off by itself.
Without pulling trigger.
Please check the headspacing
some primers were pitted
more than others.

Phone

Wayne Peck JR.
1(308)-458-2380

P.O. Box 128

MAKING IT EASIER TO COMMUNICATE™

Hyannis, NE 69350