

File Number:	11196	Arms Service number:	0902681
Last Name:	PROFESSIONAL ARMAMENTS INC	First Name:	
Street:	3895 S REDWOOD ROAD	City:	WEST VALLEY CITY
State:	UT	Zip:	84119
Home Pk:		Home Pk:	
Work Pk:		Product Type:	F A I O
Type Concern:	S	Pl PD P S C	
Concern Code:	1020		
Content:	FIRED ON BOLT OPENING		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SUP RY	Classification:	UND UND UNIC UND J
Settlement Detail:	REPLACE FC AND REPAIR AT NORMAL CHARG	Settlement Amount:	\$0.00
Date Opened Rem:	01/27/1990	Date Opened by PIS:	01/28/1990
Date of Incident:		Date Closed:	01/29/1990
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	5306012
RAMAC:	700	Date Code:	BT
Manufacturer:	REM		
Litigation:	☐	Preflighting:	☐
Obsolete:	☐		
Comments:	29 year old gun - altered adjustments and improper maintenance - Bolt release stuck down has received, bolt lift was hard - Could not duplicate customer concern - Replace FC and make repairs as needed at normal charges		
Date of Modification:	9:45:10 AM	Date of Modification:	01/29/1990

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 99-02681

INITIAL

CUSTOMER ORDER NO.

FJB

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/20/99

01/27/99

BT 1-70

6306012

700 22-250

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

SHIP TO:

PROFESSIONAL ARMAMENTS INC
3695 S REDWOOD RD
WEST VALLEY CITY UT 84119

PROFESSIONAL ARMAMENTS INC
3695 S REDWOOD RD
WEST VALLEY CITY UT
84119

CUST NO: 006063 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

Prod. Serv.

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CLE

A1

B1

IGGER GROUP

B2

E1

F1

LT ASSY.

B3

E2

F2

RREL ASSY.

B4

D1

E3

F3

C. ASSY.

B5

D2

E4

F4

OOD

C1

D3

E5

F5

ETAL

C2

IN FAULT

Altered Adjustments and improper maintenance
Bolt release stuck down as required
could not duplicate customer concern

RTS

COMMENTS

Altered Adjustments - Replace
FC and repair as needed at
normal charges

FLS 1/29/99

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

350.

PROFESSIONAL ARMAMENTS

3695 S. Redwood Rd
WEST VALLEY CITY, UTAH 84119
National Watts: (800) 845-8922
Utah Watts: (800) 845-1373
Fax: (801) 975-9333

CUSTOMER'S ORDER NO.		PHONE		DATE 7-8-99		
NAME REMINGTON ARMS COMPANY, INC.						
ADDRESS ARMS SERVICE DIVISION						
14 HOEFLE AVE.						
ILION, NY 13357-1888						
SOLD BY	CASH	C.O.D.	CHARGE	ON A/C	MOSE. RETD.	PAY-OUT
QTY.	DESCRIPTION				PRICE	AMOUNT
1	Remington Model 700 ADL					
	Caliber 250					
	Serial # 6306012					
Customer says rifle will fire occasionally when opening bolt on live round						
TAX						
TOTAL						

IVED BY

0954

All claims and returned goods
MUST be accompanied by this bill.

Thank You