

File Number:	12640		Arms Service number:	00001382	
Last Name:	REED		First Name:	JOHN	
Street:	1356 S GILBERT RD		City:	MESA	
State:	AR	Zip:	85204	Home Ph:	
Work Ph:		Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS		
Assigned To:	SANITA	Classification:	UNJ	UNJ UNC UND	
Settlement Detail:	REPAIR AT SPEC PRICE		Settlement Amount:	\$0.00	
Date Opened Rem:	12/29/99	Date Opened by P/S:	12/29/99	Caliber:	270
Date of Incident:		Date Closed:	12/30/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	B8215701	Date Code:	
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Obsolete:	☐				
Custody:		Comments:	action dirty, gummy sticky substance on trig components, trig adj screws re-set		
Time of Modification:	9:57:24 AM		Date of Modification:	12/30/99	

Serial Number: B6215701

Model ID: 700



RE00001382

12/29/99

Fired when I pushed the safety off

Upon receipt we could not duplicate the reported
concern, but found action & trigger issues. Duty
gummy and rusty action. Trigger adj screws have
been re-set. Rifle poorly maintained

26345

Repair at 50% of repair cost

Go ahead

JOHN W. REED, O.D.
DOCTOR OF OPTOMETRY
1356 SOUTH GILBERT RD. #3
MESA, ARIZONA 85204
480-545-9120

To : Remington Arms
14 Hotter Ave
Ilion, New York 13357

Dec 10, 1999

ATT: FRED SUPRY

DEAR FRED,

I called you last month about my 700 BDL #B6215701 270w. When I was unloading the gun it fired when I pushed the safety off. The round went through my ice chest and no one was injured.

Two weeks later my son missed an opportunity on a bull elk because the gun fired when he pushed the safety off as he was setting up for a shot.

My friend told me that Remington has been sued for this same problem that resulted in death. I would think that the public should be warned about this safety problem.

I hope you can resolve this serious problem. I have had this gun for many years, but if it is not safe I will have to get a different gun.

I need your assurance that this problem is fixed.

Thanks for your attention

p.s. what is the best scope mount for the 700 BDL?