

File Number:	11333	Arms Service number:	9905968
Last Name:	SEE	First Name:	JEFFREY
Street:	91 SILVER GROVE RD	City:	STOCKHOLM
State:	NJ	Home Ph:	
Work Ph:		Zip:	07460
Type Concern:	S	Product Type:	F A T
Concern:	FIRING ON SAFE RELEASE	Concern Code:	1007
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED
Assigned To:	SANITA	Classification:	UNC
Settlement Detail:	REPLACE TRIG ASSEM AT N/C	Settlement Amount:	\$0.00
Date Opened Rem:	03/03/1999	Date Opened by P/S:	03/04/1999
Date of Incident:		Date Closed:	03/04/1999
Date to Analysis:		Bullet Weight:	30/06
Model:	700	Date from Analysis:	
RAMAC:	700	Manufacturer:	REM
Custody:		Date Mfgd:	09/01/1986
		Prelitigation:	<input type="checkbox"/>
		Obsolete:	<input type="checkbox"/>
		Comments:	
Time of Modification:	10:28:38 AM	Date of Modification:	03/04/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

Prod.
Service.

ORDER

R 99-05968

INITIAL
RLP

CUSTOMER ORDER NO.

W/RECOIL PAD

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

02/23/99

03/03/99

DG 9-86

B6814744

700 30-06

BDL

ACCESSORIES

SCOPE BASE

L/SIGHTS

W/STUDS

FROM:

SHIP TO:

SEE, JEFFREY
91 SILVER GROVE ROAD
STOCKHOLM

NJ 07460

SEE, JEFFREY
91 SILVER GROVE ROAD
STOCKHOLM

NJ

07460

CUST NO:205195 C.O.D.L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

2071501

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☒ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

METAL

C2

MAIN FAULT

Upon receipt we could not duplicate the reported concern, but did note that more than normal force was required to move the safety lever.

PARTS

26345

1007

4040

COMMENTS

Repaired the complete trigger assembly at no charge

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

R06925 REV. 7/97

Remington Arms Company, Inc. Repair Instructions

Print and complete this form and mail it, along with your firearm to:

Remington Arms Company, Inc.
Attn: Arms Service
14 Hoefler Avenue
Illion, New York 13357

Name: Jeffrey C. See Model: 700 BDL
Address: 91 Silver Grove Road Serial #: B-6814744
City: Stockholm Date of Purchase: 5/18/87
State: New Jersey Zip: 07460 (if available, please attach a copy
Telephone: (Day) (800) 773-5817 of the proof of purchase.)

(Night) (673) 827-4750 Internet Request

Please describe the problem you are having with your firearm: The rifle
has a tendency to fire when the rifle is loaded, and the safety
is released. (Of course I'd much rather wait until I pull the
trigger myself) This has happened only twice since I've owned
the rifle, but it is very alarming!

Optional Information

Ammo Type: _____ Brand: _____

or Handload Specification _____ Bullet Weight: _____ Shot Size: _____

Reminders:

Record your serial number - it will help reference your repair.

Properly package your unloaded firearm. Do not ship in a hard case.

If you would like to order a box, please call our Parts Department:

800-243-9700, 9am-5pm, EST.

Do not send live/loaded ammunition with your firearm.

Remove all accessories.

Back to Obtaining Repair Service

02/11/99 8:11 AM

February 17, 1999

Remington Arms Company, Inc.
Arms Service

To Whom it may concern;

I hereby authorize you to charge up to \$100.00 on my VISA card for repair and return shipping costs.

Name: Jeffrey C. See
Credit Card Number: 4300 2300 0829 8897
Expiration Date: September, 2000

I have attached a copy of the original sales receipt. If You need any additional information from me, please feel free to call me any time using the phone numbers supplied. Also, my Email address is: jsee@warwick.net

Sincerely,
Jeffrey C. See