

File Number:	11256	Arms Service number:	9903478	
Last Name:	SPORTS SOUTH INC		First Name:	
Street:	1039 KAY LANE		City:	SHREVEPORT
State:	LA	Zip:	71115	
Work Ph:		Home Ph:		
Product Type:	F	F A T		
Type Concern:	S	PI PD P S	Concern Code:	1008
Concern:	FIRED ON BOLT CLOSING			
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED	
Assigned To:	SANITA	Classification:	UNC UNJ UNC UND J	
Settlement Detail:	REPAIR AT N/C GOODWILL		Settlement Amount:	\$0.00
Date Opened Rem:	02/04/1999	Date Opened by P/S:	02/09/1999	
Date of Incident:		Caliber:	270	
Date Closed:	02/09/1999	Bullet Weight:		
Date to Analysis:		Date from Analysis:		
Manufacturer:	REM			
Model:	700	Serial:	E6417870	
Date Code:	RR	Date Mfgd:	11/01/1997	
RAMAC:	700	Litigation:	☐	
PreLitigation:	☐	Obsolete:	☐	
Custody:		Comments:	RUST INSIDE TRIGGER HOUSING ASSEM, AND MORE THAN NORMAL FORCE REQUIRED TO MOVE SAFE	
Time of Modification:	7:52:01 AM	Date of Modification:	02/10/1999	

RECEIVING AND ESTIMATING REPORT

COMMENTS

*Product Service*ORDER
R 99-03478

INITIAL CUSTOMER ORDER NO.

FJB

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/28/99

02/04/99

RR 11-97

E6417870

700 270

ADL/SYN

ACCESSORIES

W/STUDS

FROM:

SPORTS SOUTH INC
PO BOX 51367 (ZIP 71135)
1039 KAY LN
SHREVEPORT

LA 71115

SHIP TO:

SPORTS SOUTH INC
PO BOX 51367 (ZIP 71135)
1039 KAY LN
SHREVEPORTLA
71115

CUST NO: 002049 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER MC

230145

WRITE ☐

FROM DATE

ESTIMATED

VIA

2-5

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

E5

F5

When Closing the bolt the gun fires

MAIN FAULT

*Upon receipt we could not duplicate the above concern,
but did find the trigger pin + trigger nutty. Also more than
normal force required to move the safe.*

PARTS

COMMENTS

#26345

*Repair the complete trigger
assembly at no charge*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

TO: Remington

DATE: 1/20/99

FROM: Sports South, Inc.
P.O. Box 51367
Shreveport, LA. 71135-1.

1039 Kay Lane
Shreveport, LA. 71115

1-800-881-3802

RETURN

Dear Sir:

Recently, this Model 700 270

was returned to us as defective. The reason for the return is when closing the
bolt the gun fires

Would you please inspect the merchandise for any warranty repair? If the defect is not under warranty,
please notify me of the repair cost before proceeding with the work.

Serial # E6417870

Sincerely, _____

11170