

File Number:	11894		Arms Service number:	9919059	
Last Name:	SPORTS SOUTH INC		First Name:	1039 KAY LANE	
Street:	SHREVEPORT		City:	LA	
State:	LA	Zip:	71115	Home Ph:	
Work Ph:		Product Type:	F A T		
Type Concern:	S	PI PD P S	Concern Code:	1007	
Concern:	FIRED ON SAFE RELEASE				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SANITA	Classification:	UNC	UNJ UNC UND	
Settlement Detail:	REPLACE TRIGGER ASSEM AT N/C		Settlement Amount:	\$0.00	
Date Opened Rem:	9/30/99	Date Opened by P/S:	10/6/99	Caliber:	300 ULT MA
Date of Incident:		Date Closed:	10/6/99	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	REM
Model:	700	Serial:	S6343908	Date Code:	CT
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Obsolete:	☐				
Custody:		Comments:	MORE THAN NORMAL FORCE WAS REQUIRED TO MOVE THE SAFE ARM		
Time of Modification:	8:44:46 AM		Date of Modification:	10/6/99	

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
Service

R 99-19859

INITIAL
TEFCUSTOMER ORDER NO.
11955DATE RECEIVED
09/29/99DATE OPENED
09/30/99DATE CODE
CT 4-99SERIAL NUMBER
S6343908

NEW SERIAL NUMBER

MODEL AND GRADE
700 300ULTR

SENDERO/SF

ACCESSORIES
W/STUDS

FROM:

SPORTS SOUTH INC
PO BOX 51367 (ZIP 71135)
1039 KAY LN
SHREVEPORT LA 71115

SHIP TO:

SPORTS SOUTH INC
PO BOX 51367 (ZIP 71135)
1039 KAY LN
SHREVEPORT LA 71115

CUST. NO. 002049. WILM.

ACCOUNT NUMBER

ACCOUNT NUMBER
230145WRITE ☐

PROM. DATE

ESTIMATED
10-4-99

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☒ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D2

E1

METAL

C2

D3

E4

F1

F2

F3

F4

F5

MAIN FAULT

Upon receipt we could not duplicate the reported concern,
but did note that more than normal fire was required to
move the safety cam.

COMMENTS

Replace the complete trigger
group at N/C.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

TO: Remington

DATE: 9/16/99

FROM: Sports South, Inc.
P.O. Box 51367
Shreveport, LA. 71135-1367

1039 Kay Lane
Shreveport, LA. 71115

1-800-881-3802

RETURN

Dear Sir:

Recently, this 26010

was returned to us as defective. The reason for the return is has fired twice
when being taken off safety.

Would you please inspect the merchandise for any warranty repair? If the defect is not under warranty,
please notify me of the repair cost before proceeding with the work.

Serial # 56343908

Sincerely, _____

11955