

File Number:	11218	Arms Service number:	9903032
Last Name:	VICTORIA ALL SPORTS CTR	First Name:	
Street:	1902 HOUSTON HWY	City:	VICTORIA
State:	TX	Zip:	77901
Home Ph:			
Work Ph:		Product Type:	F F A T
Type Concern:	S	PI PD P S	Concern Code:
			1020
Concern:	FIRED ON BOLT OPENING		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SANITA	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPAIR AT SPEC PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	01/29/1999	Date Opened by P/S:	02/01/1999
Caliber:	243		
Date of Incident:		Date Closed:	02/03/1999
Bullet Weight:			
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM		
Model:	700	Serial:	6238209
Date Code:	CS	Date Mfgd:	04/01/1969
RAMAC:	700	Litigation:	☐
PreLitigation:	☐	Obsolete:	☐
Custody:		Comments:	
Time of Modification:	9:30:38 AM	Date of Modification:	02/03/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

Prod.
ServiceORDER
R 99-03032

INITIAL FJB	CUSTOMER ORDER NO.					
DATE RECEIVED 01/22/99	DATE OPENED 01/29/99	DATE CODE CS 4-69	SERIAL NUMBER 6238209	NEW SERIAL NUMBER	MODEL AND GRADE 700 243	BDL
ACCESSORIES W/STUDS						

L/ REAR SIGHT

FROM:

VICTORIA ALL SPTS OTR
1902 HOUSTON HWY
VICTORIA

TX 77901

SHIP TO:

VICTORIA ALL SPTS CTR
1902 HOUSTON HWY
VICTORIATX
77901

CUST NO:006841 WILM L

ACCOUNT NUMBER 2293001	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED 2-1-99	VIA UPS
GUN CONDITION ☐ NEW ☐ LIGHTLY WORN ☒ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED		REPAIR CHARGE EXCISE TAX INSURANCE UPS PARCEL POST TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

SEND TO Prod. Service.

Upon receipt we could not duplicate the reported concern, upon removal the action was dirty & the trigger very heavy. Action has been cleaned with
Moly 1969

#26345

COMMENTS

Replace the Composite trigger assembly &
Clean the action at 1/2 the normal
cost
JG added

REPAIRMAN C.R.	PROOF	CLEAN ✓	TEST ✓	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD5925 REV. 7/97

VICTORIA'S ALL-SPORTS CENTER

A Division Of Victoria Army Sales
1902 Houston Hwy.
VICTORIA, TEXAS 77901

FROM:
VICTORIA ALL-S
1902 HOUSTON
VICTORIA, TX 7

TO: Remington Arms
14 Hoefler Avenue

TO: Remington
14 Hoefler
Lion, NY

ILion, NY 13357

13357

MODEL# 700 SER# 6238209 SIZE .243win MANU. Remington

DESCRIPTION R.F/e

DEFECT The rifle fires when you try to unload. The
customer shot hole in kitchen table & floor when he tried
to unload them. Please check them out and repair
for customer.

CUSTOMER Marvin Rothbauer TELE. #

SHIPPING COST \$ ADDITIONAL FEES \$

THANK YOU,

K

SHIPPING DEPT.
(512) 575-0655