

File Number:	11306	Arms Service number:	9905051
Last Name:	WAL MART 1107	First Name:	
Street:	1205 HWY 165 SOUTH	City:	OAKDALE
State:	LA	Zip:	71463
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F A T O
Concern:	PI PD P S C	Concern Code:	1007
FIRE ON SAFE RELEASE			
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SUPRY	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPLACE FC AT NORMAL CHARGES	Settlement Amount:	\$0.00
Date Opened Rem:	02/10/1999	Date Opened by P/S:	02/25/1999
Date of Incident:		Date Closed:	02/26/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	E6282038
RAMAC:	700	Litigation:	
Custody:		Prelitigation:	
		Obsolete:	
		Manufacturer:	REM
		Date Mfgd:	07/01/1996
Comments: Could not duplicate concern - Upon removing the stock, the inside was wet - with rust deposits on the action and the FC - Replace FC - clean and inspect rifle at normal charges			
Time of Modification:	10:30:25 AM	Date of Modification:	02/26/1999

RECEIVING AND ESTIMATING REPORT

COMMENTS

*Product
service*ORDER
R 99-05051

INITIAL CUSTOMER ORDER NO.

FJB 0111071187

DATE RECEIVED

02/14/99

DATE OPENED

02/20/99

DATE CODE

OQ 7-96

SERIAL NUMBER

E6282038

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

ADL

ACCESSORIES

W/STUDS

FROM:

WAL MART 1107
1205 HWY 165 SOUTH
OAKDALE

LA 71463

SHIP TO:

WAL MART 1107
1205 HWY 165 SOUTH
OAKDALELA
71463

CUST NO: 071985 WILM L

ACCOUNT NUMBER

2293001

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

2-24-99

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

PLEASE NOTE: IF YOU RECEIVE AN ESTIMATE OF WORK TO
BE DONE AFTER THIS ACKNOWLEDGEMENT, IT MUST BE
APPROVED BY SIGNING AND RETURNED TO US BEFORE WE CAN
START THE WORK OUTLINED ON THE ESTIMATE.

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

D3

E5

F5

MAIN FAULT

*As received Action was rusted, FC Rusted
inside stock still wet with rust deposits*

PARTS

COMMENTS

*Replace FC, clean and check
function at normal charges -
FLS 2/26/99*

REPAIRMAN

RBS

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 7/97

FIREARM REPAIR TAG

075598

No.	1107
	2/4/99
	Remington
	700
	255
Code	00 472 00 874 78
No.	
No.	E 6 28 2038
on Sending	
Repair	
CUSTOMER GUN	☒ Yes ☐ No
Name	SAMUEL Gobert
Address	P.O. Box 754 Dberlin, LA 70455
Phone	318-439-2558
Reason for Return	Be specific. List the problem with the gun. When going from Safe to Fire Gun Fires. DOES NOT do this EVERYTIME
THIS AREA FOR CLAIMS USE ONLY	
SENT TO	
DATE SENT	

CLAIMS COPY

TOTAL	275.40
CASH TEND	280.00
CHANGE DUE	4.60

TC# 2531 9876 8063 9766 1243 4
THANK YOU FOR SHOPPING AT WAL-MART
11/02/98 16:27:07