

File Number:	9954	Agency Number:	9722700
Last Name:	CURTIS	First Name:	JIM
Street:	7503 OLIVE DR	City:	BAKERSFIELD
State:	CA	Zip:	93308
Work Ph:		Home Ph:	
Product Type:	F	F A T	
Type Concern:	S	PI PD P S	Concern Code:
Concern:	FIRED ON SAFE RELEASE		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SANITA	Classification:	UNJ
Settlement Detail:	REPAIR AT SPECIAL PRICE	Settlement Amount:	\$0.00
Date Opened Case:	12/20/97	Date Closed by:	12/22/97
Date of Incident:		Date Closed:	12/22/97
Date to Analysis:		Date from Analysis:	
Model:	7	Serial:	7600144
RAMAC:	7	Date Code:	RC
Custody:		Date Mfgd:	11/1/82
Litigation:	☐	PreLitigation:	☐
Obsolete:	☐	Comments:	
Time of Modification:	11:00:02 AM	Date of Modification:	12/22/97

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDE

R 97-22700

INITIAL

CUSTOMER ORDER NO.

ATTN JERRY BEIGH

JJM

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

12/18/97

12/20/97

RC 11-82

7600144

7

7MM08

ACCESSORIES

SCOPE BASE

W/STUDS

L/SIGHTS

FROM:

SHIP TO:

CURTIS, JIM
7503 OLIVE DR
BAKERSFIELD

CA 93308

CURTIS, JIM
7503 OLIVE DR
BAKERSFIELDCA
93308

CUST NO: 179965 C.O.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NO.

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE☐ MARRED

REPAIR CHARGE

28.00

EXCISE

TAX

INSURANCE

UPS

8.00

PARCEL POST

TOTAL

36.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

E1

F1

BOLT ASSY.

B3

E2

F2

BARREL ASSY.

B4

D1

REC. ASSY.

B5

D2

E4

F4

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Upon receipt we could not operate the weapon, but we found the trigger bent, and the gun safety cam working very sluggish from being covered with a heavy sticky substance. Gun was also not a good cleaning. Life pretty maintained.

COMMENTS

Replace the bent trigger cam.
& clean action at 1/2 the normal
up to test. Go ahead

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD8925 REV 7-97

JERRY BEIGH PER. NEVIN DUPLESSIS

(SR. #7600144)

DEAR JERRY: THE MODEL SEVEN RIFLE
ENCLOSED ACCIDENTLY FIRED.

THE PROCEDURE BEFORE THE FIRING WAS
AS FOLLOWS. I LOADED A ROUND IN
THE CHAMBER FROM THE MAGIZINE.

PUSHED THE SAFETY TO FIRE POSITION,
ATTEMPTED TO PULL THE TRIGER IT WAS
HARD AND DIDNOT LET OFF. I TURNED
THE GUN SIDWAYS TO SEE THE TRIGER
AND SAFETY POSITION. WITH MY HAND
ON THE PISTOL GRIP AND TRIGER FINGER
OUT OF THE TRIGER GUARD THE GUN
FIRED. APPROXIMATELY 5 SECONDS AFTER
I FIRST ATTEMPTED TO PULL THE TRIGER.
THANKS FOR YOUR ATTENTION IN THIS MATTER.

Jim Curtis

TIME 4:00 PM

AIR TEMP. 55-60° F

ELE. 5000' IN

LOCATION

APPR. 50 MILES

NE OF BKEF. CA.

DEER HUNTING

JIM CURTIS

7503 OLIVE DR.

BAKERSFIELD CA. 93308

PHONE # (805) 838-2226

P.S. THE GUN FIRED 5 ROUNDS AFTER
THE INCIDENT WITH NO PROBLEMS