

Fred Kuhn 40X #4

- ✓ Loading platform poor
- Muzzle too heavy
- ✓ Stock is not high enough for scope.
- Stock O.K. for Iron Sights.
- Trigger feels good. O.K.
- ✓ Do not like flat on bottom of forearm - should be rounded.
- No slip butt plate - good.
- Grip O.K.
- Do not like rim on forearm stop.
- ✓ Safety too loose.
- Should leave off rear scope block and put in plug screws.
- ✓ Ebl. should be counter bored like 37.
- We should use higher sight base for front sight.

1/26/54