

cc: R.A. Williamson
S.M. Alvis
~~W.E. Look~~
H.J. Hackman
V.G. DeReus
A.D. Kerr
F.T. Plunkett
Estimate File #2512

Ilion, New York
October 6, 1964

H. K. PAULKNER (2)
ATTENTION: C. L. JONES

MODELS 700 AND 600 SAFETY MARKINGS FOR EXPORT

Estimates indicate an additional factory cost of ninety cents (\$.90) per gun for the proposed safety position markings.

Receiver tangs under the safety will be engraved as follows:

1. A letter "S" in the rear position indicating "Safety On".
2. A letter "F" in the front position indicating "Ready to Fire".

Estimated costs are based on these assumptions:

1. Custom Repair will unpack warehouse guns.
2. Custom Repair will engrave and paint markings.
3. Custom Repair will repack and label for warehouse.

R. A. Williamson
Works Manager

R. L. Hall
R. L. Hall, Supervisor
Methods & Standards Section

RFKerr:am