


P. EX. E

PRODUCTION OPERATOR GAGING CONTROL
FLOW CHART
GENERAL PROCEDURE 1 - FOR PRODUCTION



MMW/eb
7-13-61

MW/cw
10-11-66