W100

c. J. G. Williams
J. E. Dickey
Fred Flunkett
Hugh Wilson
Pete Olfert

Berkeley, California November 13, 1969

TO:

PETE MORGAN

PROM:

D. LEE HRAUN

SUBJECT:

CORRESPONDENCE REGARDING MODEL 700 TO HUGH WILSON OF NOVEMBER 5, 1969

I answer your letter to Hugh Wilson in regard to the Model 700 7 mm magnum rifles not handling competitive ammunition.

Hugh Wilson took the three guns in question to Bob and Duane's Gun Shop, one of our recommended repair stations, and had them repaired.

The face of the bolt had burrs so that the rim of the cartridge would not fit and the chamber was less than minimum measurements and had to be polished out to a larger size so the cartridges would fit. These three complaints were corrected by our repair station.

I have just returned from Los Angeles and Pete Olfert advises me there has been a rash of complaints on the feeding of ammunition in our Model 700. One such gun would work fine with a full magazine of ammunition, but with only one cartridge in the magazine, it would throw the shell out instead of feeding it into the bancel. Packmayr took care of several complaints of this type.

This is the only answer we can give you in regard to your above subject correspondence.

D Le Doraun

D: LEE BRAUN

dlb;ms