FOR COMPANY USE ONLY

FOOTNOTES

1. A gun writer, commenting on the test of a similar Weatherby rifle, noted a significant improvement in accuracy when the plastic plate under the recoil lug was reduced in thickness enough to permit (presumably) contact between the receiver and stock at this filled recess.

Hagel, Bob, "Special Test Report, Vanguard", <u>The Handloader</u>, January-February, 1970, page 41.

- 2. It is the author's personal opinion that, aesthetically, the pistol grip pattern could be improved considerably by making the borders more nearly conform to the stock outline.
- 3. The trigger assembly is attached to the receiver with two flat head socket head screws at either side of a transverse pivot. This method allows adjustment of the amount of engagement between the sear and the cocking piece. Since this method appears to be unnecessarily expensive, it is felt that this attachment method is employed to adapt a preexisting trigger assembly (perhaps from a vendor) to this rifle.

REMINGTON ARMS COMPANY, INC