

✓ M. H. Walker - Ilion  
R. A. Baldwin  
R. P. Kelly - Ilion  
Lloyd Fox - Ilion  
Field Service File

Bridgeport, Connecticut  
April 9, 1973

TO: F. E. MORGAN

FROM: E. G. LARSON

BOLT GUN SAFETIES

You will recall in our last Field Service meeting at Ilion, the subject of the safety on our bolt guns was brought up because some customers complained that it was unsafe to take the safety off to unload the gun.

At the N.R.A. Convention, Dick Baldwin and I checked all the bolt guns of our major competitors, and all worked similarly to the 700.

We would like to point out, however, the Model 70 has an indexed stop on it and does not require the precision positioning pointed out by Mike Walker.

Would suggest Mike investigate possibility of including an index notch, if at all possible, and that the instruction folder be updated, clearly advising how the operation should be performed.

*E. G. Larson*

EGL:tk