

Remington-
UMC

REMINGTON ARMS COMPANY, INC.

PETERS
P

MANUFACTURERS OF
SPORTING FIREARMS, AMMUNITION

SPORTING FIREARMS, TRAPS, TARGETS, NEW YORK
AMMUNITION, BRIDGEPORT, CONNECTICUT
LONGHORN, ARKANSAS
CABLE: HARTLEY, BRIDGEPORT
TELEX: 964 201 STRAFFORD CONN

TRAPS

TARGETS

BRIDGEPORT, CONNECTICUT 06602

PETERS CARTRIDGE DIVISION
BRIDGEPORT, CONNECTICUT
TARGETS, FINDLAY, OHIO
ADA, OKLAHOMA
ATHENS, GEORGIA

December 5, 1973

Dear Gun Owner:

This letter will confirm receipt of your telephone call to our toll-free number regarding the recall of certain Remington Bolt Action rifles and pistols. We would appreciate your checking the following list to verify that your gun is involved:

RECALLED GUNS

All Remington Model 600's

All Remington Model 660's

All Mohawk 600's - except those with a serial number starting with an "A".

All XP-100's, with a serial number below 7507984, except those with the prefix "A" or "B" before the numbers.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected - and modified if necessary. If you do not already have the name and address of the nearest Remington recommended gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

In all states except Connecticut (toll free):

1-800-243-2870

In Connecticut (toll free):

1-800-972-9379

The operator will ask for the model and serial numbers of your gun. Please have both available when you call.

If it is necessary for you to ship your gun to the nearest repair station rather than deliver it in person, do so "COLLECT".

If you have an XP-100 that is being recalled, please send it "COLLECT" to Remington at the following address instead of to one of the gunsmiths:

Remington Arms Company, Inc.
Arms Service Division
Ilion, New York 13357

We sincerely regret any inconvenience you may have had in connection with this recall, and we appreciate your cooperation.

Sincerely,

REMINGTON ARMS COMPANY, INC.

IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

**Owners of the above guns should contact
one of the following gunsmiths:**

In Anchorage	In Anchorage	In Fairbanks
Howard's Gun Shop	Bill's Gun Shop	Dixon's
528 Fifth Avenue	8729 Lake Otis Parkway	261 College Road
Anchorage, Alaska 99501	Anchorage, Alaska 99507	Fairbanks, Alaska 99701
(907) 272-4570	(907) 349-1312	(907) 458-8742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.