

Barnet, V.P. of R.I.D., then even V.P. of
he has been V.P. of R.I.D.

Notes on Barnes Records

- M/700 Final assembly + Final inspection
- ① Records for process to 3/71 - includes step 17
in adjustment of overhaul to remove the wheel
 - ② Records for 3/73 - 11/80 - includes step 17 on
overhaul adjustment 3/27/75 record
has step 18 - Final test
Has them test in 3/73 double change form
.0074 .005 clearance

Nothing in pre/75 records about a test of
safety = to safety performance check

11/80 records have .006 shown

M/700 Trigger Assembly.

Records 1972 to 8/79 suggest migration need
to get material to spec
8/79 - 8/80 - Process records have
W.A.W. involved in them -
Records refer to .006 stem for connector

Refers to Filing Fixture for filing of trigger

11/80 funds has RLG (Rt. 2nd archs)

Proof, Test, Target-

Calley Test - Process records 10/75-4/79 -
suggested that in this time period of tests
safety performance type test + bench test were both
performed on rifles in gallery -

* Best tests 1967-10/75 - Not indicate
even safety performance type test was performed
(this not consistent of testimony in my
interrog of testimony)

Group initiation documents for 11/80 by great
Proof, test + target records

Microfilm Records on LERs

Similar in some as Arms Sales Review depression
where ET hanson, JE Presser
Published in letters to customers