

SPECIFICATIONS, TECHNICAL INFORMATION & SERVICES

1. Owner's Manual for Models 40XR - 40XC -- 90% complete.
2. Safety copy change for M/700 Owner's Manual has been requested and written by Legal Department. Inserts with this information have been printed in plant to use up manuals already printed. The new copy will be incorporated into manuals at next reprint. This has again been revised by Legal and will be printed as soon as possible.
3. Mutilated or otherwise unsatisfactory drawings are being redrawn when time permits.
4. Alter 3200 Owner's Manual exploded view and parts list to latest revision.
5. Upgrading of microfilm cards has been started.
6. Wonder Trap service manual has been revised to "B" Model and has been delivered to printer.
7. Suggestion re: unloading of M/700 BDL Magazine by Legal Dept. has been approved by Custom Shop. Will be used in next reprinting.
8. Review all Remington Logo marking drawings and alter if necessary.
9. Wood identification-label for 552 - 572 -- Completed.
10. Mechanicals for hang tags requested by planning are complete.
11. Quote submitted to M. F. DeMayo for preparation of mechanicals for Union contract booklet.
12. Drawings and numbers for alternate wood have been provided and included in parts lists.
13. M/540NR Owner's Manual has been sent to Marketing-Legal for approval.
14. Prepare new mechanicals for extra barrels package labels. Requested by Legal Dept. to include new Remington logo.
15. Signs for Ins Vends Gun Dept. completed.

FCM:10