

REMINGTON ARMS COMPANY, INC.

Field Service
Bpt., Conn.

GUNSMITH CALL REPORT

From _____ Reporter _____ Date 10/20/70

Address _____ Zip _____
Street City State

Name of Business _____ Dealer () Large () Small ()

Persons Interviewed _____ Position _____
Mr. Warren Melchow Gunsmith

GENERAL DISCUSSION

At this shop I was handed a .270 in which would fire when the safety was released--the gun had just been received and Mr. Melchow had not been able to check it. In removing the action from the stock found that all the screws in the trigger assembly had been adjusted with the seals broken and in removing the assembly a broken piece of the connector fell out. After installing a new connector and adjusting the trigger corrected the condition. Also a .45 S&W gun that would only take one shell in the magazine--a piece of the follower latch had broken and lodged in the magazine--along with being one of the early types where the action spring stop was started and not pinned gave Mr. Melchow a problem for he had never attempted to change one of this type before to the SPECIFIC PROBLEMS. All the other items mentioned here were the usual--some chips or old loose-end supports breaking along with a few feed rollers. This shop is a variety repair shop for him, along with a couple of the other kinds which make a large volume of work here.