rocall of Models 600, 660, Mohawk 600, and XP-100 bolt action guns, produced prior to February, 1975, because of a possible safety problem.

As a Remington Recommended Gunsmith, your shop has been listed with an 800 Enterprise message receiving center in Atlanta, Georgia. Upon receipt of a call from an owner of one of the guns involved, the message receiving center will direct him to the Remington Recommended Gunsmith located geographically nearest to him, for repair of the gun. We estimate you may receive up to 200 of these guns for repair.

To provide the simplest and most positive repair, you will be supplied with new trigger assemblies for replacement of the original. The repair will be done at no charge to the gun owner.

Our Arms Service section reports that the replacement of the trigger assembly can be made in 7-1/2 to 10 minutes. Based on this, we plan to allow you a \$5.00 bench charge for this work. Where transportation or other special handling costs are involved, we will reimburse you.

While full details have not been developed, we did want to give you this advance notice, and we will contact you in the very near future, covering all details.

Meanwhile, should any guns be returned to you, please record the date, name, address, zip code, and serial number and caliber of the gun, and hold until you have our instructions.

"CONFIDENTIAL by Stipulation and order entered in Tsachalis v. Remington Arms, Inc., et al., Supreme Court of the State of New York, t Westchester, Index No. 9344/95"

## IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefer "A" or "B" before the number.

Owners of the above guns should contact one of the following gunsmiths:

In Honolulu Honsport, Ltd. 1365 Colburn Street Honolulu, Hawaii 96817 (308) 523-3020 or (808) 949-5591

In Honolulu The Thom Company, Ltd. King & Smith Streets Honolulu, Hawaii 96817 (508) 535-6764 In Hottokaa Ka Pu Kapili P.O. Box 745 Honokaa, Hawaii 98727 (608) 775-02-14

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Cans covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

"CONFIDENTIAL by Stipulation and order entered in Tsachalis v. Remington Arms, Inc., et al., Supreme Court of the State of New York, County of Westchester, Index No. 9344/95"

## MESSAGE TO OWNERS CEMINICATION MODEL 600 AND 660 RIFLES, OHAWK 600 RIFLES, AND MP-100 PISTOLS.

Under certain unusual circumstances. the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is. therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any

XP-100 pistols with a social number below 7507984, except those with the prefix "A" or "B" before the number.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected—and modified if necessary. To obtain the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

In all states except Georgia (toll free):

1-800-241-8444—ask for operator 61 In Georgia (toll free):

1-600-282-1333—ask for operator 61

In Canada (collect):

519-621-7271

amolic in spite of its fearful fumes. my mother's hatred of the habit, and the expense to my non-existent budget. But somehow the idea of sitting there, pulling tentative, pracrice smoke rings until my tongue blistered added the final touch to my vision of myself as a would-bemountain man. By just closing my eyes I could be dressed in buckskin -fringed, of course-and palavering in pretty good fashion complete with the two or three gestures of "tinger talk" I had picked up in my brief encounter with the Boy Scouts.

In those days you could buy at any good country general store a pair of what was known as "overthe-knee" boots. How far over de-pended on how tall you were, but they were never over enough for wading in anything more than a rivulet. Any retrieving chores in my wind-sheltered pothole necessitated going in over the tops; why I didn't just take the boots oil and wade wet escapes me now, but I know I never did. No doubt getting wet and a little bit cold only enhanced the mood of wilderness and adventurefart and parcel of being out on your

n, surviving against the elements lith home and a glowing wood bearing Litchen stove a brisi, hour's wall, away, just the right distance in the dark to have its owl-calling moments of chilling thirds before the yellow lights of the farminouse appeared with their promose of warmth. Security, and a homeomic med,

My pondhole delivered the occasional duck before freezing over. early in November, and now and then a gray aquirrel or rabbit, but that was the small end of its purpose. To a yearling farmboy with an imagination that hordered on runaway, it served magnificently as a frontier; at times an ocean, more often an immanied mountain bivouse, or the headwaters of a wilderness river. It lent credence, in its way, to the visions of Fludson's Bay, the Rocky Mountains, and cager comparisons with the lives of Carson and Boone, Lewis and Clark, Bridger and Green. My ducks were messengers from places nuknown and truly wild. passing through from what I believed to be moose and caribon country to an equally believed tropies filled with anacondas and husbmasters-how I wished then, and still do, that I could see for myself the lands they saw and lived in. And their just being there, those pintads and blacks, in front of my oak and hazel and cedar blind, created a belief in things I could only dream about-their wings whispered that all these things were real and true; that they had seen and known places and creatures that would beggar my wildest dreams.

My visions of exploring these an exact dopticate of my father's you effected for no then, of course); that most exquisite piece of machinery known as a Winchester model 97 hammer pump. With this in hand, I would be fearless, unconquerable, and completely selfsufficient . . . anywhere. Ud sneak it out and shack it when no one was around and marvel at how perfect it sounded as the various roots and stides drew a shell from the magazine up into the chamber, the bolt slid the hammer back as slick as anything, and it all closed with consummie authority and sat poised to strike with a power that to me was akin to lightning. Then I would work it empty again, case the ham-mer back to half, the way Pop left it, wipe it off, and place it back in the closet where it always sat.

Before I was big enough to handle, it. Pop traded the 97 for another pump he never liked as well. And then we moved. The fact that the pondhole and the pump are gone are indisputable. But I still have my pintails and the occasional black . . . and have now and then gone where, no doubt, some Indian has walked before. The dreams have shrunk somewhat and the night-calling owls bring another Lind of chilling thought . . . a moment beyond the help of even Pop's old model 97. But the linding sound of wings can

wandrous tracts never failed to in "CONFIDENTIAL by Etipulation and cinde the company of what was the analytical logical confidence of places logical confidence

"Teechelia. v. Remington Arms, Inc., ci al., Supreme Court of the State of New York, County of Westchester, Index No. 9344/95",

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

> Owners of the above guns should contact one of the following gunsmiths:

In Anchorage Howard's Gun Shop 528 Fifth Avenue (907) 272-4570

In Anchorage Bill's Gun Sitop 8729 Lake Otis Parkway Anchorage, Alaska 99501 Anchorage, Alaska 99507 Fairbanks, Alaska 99701 (907) 349-1312

In Fairbanks Dixon's 261 College Road (907) 456-6742

If the location of the nearest gunsmith is not convenient for personal. delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

In the continental United States, write to: Remington Arms Company, Inc., 939 Barrum Avenue, Endgeport, CT 06002.

> "CONFIDENTIAL by Stipulation and order entered in Eachalis v. Remington Arms, Inc., et al., Supreme Court of the State of New York, County of Westchester, Index No. 9344/95"

# TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 650 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected—and modified if necessary. To obtain the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge). phone one of the following numbers: "CONFIDENTIAL by Stipulation and

In all states except Georgia (toll free). Tsachalis v. Remington Arms,

1-800-241-8444—zsit for operate, @Lal., Supreme Court of the State of New York, County of

1-800-202-1888—ask for oper Westell Eter, Index No. 9344/95"

In Canada (collect): 519-621-7271

Another important message to all gun owners.

Much has been written on firearms safety in general, and gun safeties, in particular, but we feel that a most incisive statement is contained in the NRA Hunter/Safety Handbook: "No hunter should depend wholly on the safety to prevent accidental firing. The safety is meant only to supplement proper gun bandling."

Rennigrou Arms Company, Inc.

80F12

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge. The installation of a new trigger assembly will remedy this situation. Remingion is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk

Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

### Owners of the above guns should contact

Howard's Gun Shop 526 Fifth Avenue Anchorage, Alaska 99501 (907) 272-4570

In Juneau C & S Gun Room 94 Mile Clacier Highway Juneau, Alaska 99503 Telephone: 907-789-2650 Mailing address:

one of the following GOMENHES:

in Inchange Order entered in An Inchorage Order entered in 18729 Land Office of the Super Order entered in 18729 Land Office of the Inches of t Anchology, Apple of New York, County of 19344/95" in this banks of New York, County of Dixon's IChester, Index No. 9344/95" (907) 45G-S742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

P.O. Box 2415 Note: ship regular mail, NOT U.P.S.

Reministrations Giffo remineron arms company, nic. • rubics relations • unideffort, connecticut escor

### RELEASE

ena peluaca — Ib	CHED INTELY
------------------	-------------

Company, Inc., announced today that under certain unusual circumstances on some of its center fire bolt action firearms, the safety selector and trigger could be manipulated in such a way that subsequently moving the selector to the fire position could result in accidental discharge. Remington firearms involved are Model 600, 660 and Mohawk 600 rifles and XP-100 pistols manufactured prior to February 1975.

The difficulty can be corrected by installation of a new trigger assembly. In view of the potential safety hazard, the Company is recalling all of these guns produced prior to February 1975 for inspection and modification as required.

Efforts are being made to contact owners of these gunsIndividuals who have Model 600, 660 and Mchawk 600 rifles or

XP-100 pistols involved in the recall should write to Remington
rms Company, Inc., Bridgeport, CT 06602, or call the following
toll free number for information on procedures:

In all states except Georgia:

800-241-8444 - Ask for Operator 61

In Georgia:

100F12

order entered in

Tsachalis v. Remington Arms

Inc., ct al., Supreme Count of
the State of New York, County of
Westchester, Index No. 9344/95"

Customers should give the operator the model and serial numbers of their gun when calling.

Serial numbers involved in the recall are as follows:

Remington Model 600s -From Serial #0001 to 131,552

Remington Model 660s -From Serial #0001 to 131,552

Mohawk 600s -From Serial #6,200,000 to 6,899,999

Remington Model 660s -From Serial #6,200,000 to 6,899,999

Remington XP-100 -From Serial #0001 to 7,508,983

"CONFIDENTIAL by Stipulation and order entered in Tsachalis v. Remington Arms, Inc., et al., Supreme Court of the State of New York, County of Westchester, Index No. 934785

*forminglome* City remains a laws company, inc. • puello relations • exideepoat, connectious office

( )	£	ìi	5	ÆŠ,	6	ļ:· — · ·
إنهسم	į	ġ	F	F 13		(
li li	ř	-	·	<i>ii</i>	السيسة	f

	•	THE PROPERTY OF THE PROPERTY O
חח	DELEASE	IMMED DATELY

BRIDGETORT. Ct., October 25, 1978 — On October 23, 1978, a product liability case against Remington Arms Company. Inc., and one of its dealers was settled for \$6,800,000 by Remington's insurance carriers. The case involved an alleged accidental discharge of a Mohawk Mcdel 600 rifle manufactured by Remington.

Injuries to the plaintiff were extremely serious, leaving him partially paralyzed. The plaintiff alleged that at the time the gun fired the trigger was not pulled. Remington's investigation indicated that this was unlikely but possible due to the fact that under certain unusual circumstances the safety selector and brigger could be manipulated in such a way that subsequently moving the selector to the fire position could result in accidental discharge. Settlement costs are substantially covered by the Company's liability insurance.

A recall program has been initiated in connection with Mohawk Model 600 rifles and Remington Model 600 and 660 rifles and XP-100 pistols manufactured prior to February 1975.

╣┼┼

120F12

CONFIDENTIAL by Stipulation and order entered in Tsachalis v. Remington Arms, Inc., et al., Supreme Court of the State of New York, County of Westchestor, Index No. 9344/95