

Remington.

REMINGTON ARMS COMPANY, INC.

Chron
PETERS
OU POINT

SPORTING FIREARMS
TRAPS
POWDER METAL PARTS
ILION, NEW YORK
AMMUNITION, BRIDGEPORT, CONNECTICUT
LONOKE, ARKANSAS

MANUFACTURERS OF
SPORTING FIREARMS, AMMUNITION
TRAPS TARGETS
ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

November 29, 1977

PETERS CARTRIDGE DIVISION
BRIDGEPORT, CONNECTICUT
TARGETS, ADA, OKLAHOMA
ATHENS, GEORGIA
RINDLAY, OHIO
CABLE—HARTLEY, BRIDGEPORT

James E. Hamby
CW3, USA
Chief, Firearms Div.
U.S. Army Criminal Inv. Lab. - CONUS
Fort Gordon, Ga. 30905

E.F. Barrett
Xc: N.S. Wilson
E. Sienkiewicz
C.B. Workman

Dear Sir:

Your letter re our serial numbering has been forwarded to this department.
We hope the following information will be satisfactory:

<u>Model</u>	<u>Serial # Location</u>	<u># Series</u>
3200	Bottom of Frame	OU 4,000 - OU 999,999
1100	Left Rear Receiver	M000001V - M999999V
870 (12, 16, 20 Ga.)	Left Center Receiver	T000001V - T999999V
870 (28, 410 Ga.)	Left Rear Receiver	T000001J - T999999J
Mohawk 48 (12 Ga.)	Left Rear Receiver	5250001 - 5499999
Mohawk 48 (20 Ga.)	Left Rear Receiver	5875001 - 5999999

Please note that in above Models 1100 and 870, prefix letters are those in current use. Earlier serial numbers had no prefix letters and future guns will be stamped with different prefix letters, such as N (Model 1100) and U (Model 870). Suffix letters shown denote gauge of gun.

700	Front Left Receiver	A6200000 - A6899999
Mohawk 600	Front Left Receiver	A620 0000 - A6899999
40XB	Front Left Receiver	038743B - 099999B
40XR	Front Left Receiver	038743R - 099999R
40XC	Front Left Receiver	038743C - 099999C
742	Center Left Receiver	A6900000 - A7499999
760	Center Left Receiver	A6900000 - A7499999
XP100	Front Left Receiver	A7500000 - A7509999
788	Front Left Receiver	A6000000 - A6199999
552	Right Rear Receiver	1400000 - 1999999
572	Right Rear Receiver	1400000 - 1999999

R2507707

James E. Hamby

-2-

November 29, 1977

<u>Model</u>	<u>Serial # Location</u>	<u># Series</u>
540-X	Front Left Receiver	1000001 - 1299999
541-S	Front Left Receiver	1000001 - 1299999
580	Front Left Receiver	1000001 - 1299999
581	Front Left Receiver	1000001 - 1299999
582	Front Left Receiver	1000001 - 1299999
Nylon 66	Front Left Receiver	A2100000-A2599999
Mohawk 10C	Front Left Receiver	A2100000-A2599999

Please note that in above models where prefix letters "A" are shown, these letters are those in current use. Earlier serial numbers had no prefix letters and future rifles will be stamped with different prefix letters, such as "B".

Very truly yours,

C.B. Workman, Manager
Ilion Research Division

By

F. G. Hart

F. G. Hart

Technical Writer & Specif. Engr.

FGH:T

Remington Arms Company, Inc.

R2507708