

P.I. YES GUN EXAMINATION REPORT NUMBER: 155 MODEL: 700 A

GENERAL CONDITION: FAIR R #: 25733

OUTSIDE WORK: SCOPE BASE ADDED DATE: 10-3-79

FIRE AMMO TYPE: NOT KNOWN FROM: LIBERTY MOUNTAIN BUILDING 30

& CONDITION: 8201 E. PREVIOUSLY ENGAGED IN CIVIL GUN #: 6853510

PROOF: REM INSP.: 62 TEST: 97 CODE: CZ-4-75

HEADING: OK GA./CAL.: 2576

BREECH OPENING: OK CHECKED BY: M. H. H. H.

RECOIL SHOULDERS: OK APPROVED: SOH 10/19/79

CHAMBER: OK APPROVED: POA 10/19/79

TEST: OK APPROVED: R. B. 10-18-79

COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: SOH 10-18-79

SMALL DENTS IN STOCK

SMALL DENTS IN STOCK - Barrel added in stock

outside of stock. Barrel had removed

01

COMPLAINT: GUN WENT OFF WHEN CHAMBER WAS

NOT REMOVED

INCIDENT: WAS IN STOCK AT 10-18-79

CHAMBER WAS REMOVED

COMMENTS: Trigger assembly adjusted outside factory. Sealant

missing on 3 screws. Trigger adjustment screws have been

loosened out reducing trigger pull. Trigger pull 1 1/4"

Remington screws 3" to 5". No adjustment on trigger

CONFIDENTIAL by stipulation and order entered in
Tsachalis v. Remington Arms,
Inc., et al., Supreme Court of
the State of New York, County of
Westchester, Index No. 9344/95"