

Date 10-2-80

Tester _____

DRY CYCLE SUMMARY

(For deviation attach supplementary sheet)

(2)

Previous Cycles 7500

Cycle Rate _____

TEST: SAFE OIL ORL SAMPLE 2

2522 Cycles Total 10000

Sear Lift
Trigger Pull 6.50 - 6.50 - 6.25 - 6.25 - 6.25

Observations:	Force for Safe On	Force for Safe Off	10 Rd. Function	Safe Operation
	<u>4.52</u> <u>4.52</u>	<u>4.06</u> <u>3.12</u>		
	<u>4.50</u> <u>4.50</u>	<u>3.5</u> <u>4.0</u>		
	<u>4.5</u>	<u>4.0</u>		

2500 Cycles Total 12500

Sear Lift
Trigger Pull 6.8 - 6.50 - 6.50 - 6.50 - 6.50

Observations:	Force for Safe On	Force for Safe Off	10 Rd. Function	Safe Operation
	<u>4.52</u> <u>4.52</u>	<u>4.0</u> <u>4.0</u>		
	<u>4.5</u> <u>4.5</u>	<u>3.75</u> <u>2.75</u>		
	<u>4.0</u>	<u>3.75</u>		

2500 Cycles Total 15000

Sear Lift
Trigger Pull 6.0 - 6.25 - 6.50 - 6.25 - 6.25

Observations:	Force for Safe On	Force for Safe Off	10 Rd. Function	Safe Operation
	<u>4.0</u> <u>4.0</u>	<u>4.0</u> <u>3.12</u>		
	<u>4.0</u> <u>4.0</u>	<u>3.22</u> <u>3.25</u>		
	<u>4.0</u>	<u>3.25</u>		

2500 Cycles Total 17500

Sear Lift
Trigger Pull 6.75 - 6.50 - 6.25 - 6.50 - 6.25 Break After Contact

Observations:	Force for Safe On	Force for Safe Off	10 Rd. Function	Safe Operation
	<u>4.52</u> <u>4.0</u>	<u>4.0</u> <u>3.12</u>		
	<u>4.5</u> <u>4.5</u>	<u>4.0</u> <u>1.5</u>		
	<u>5.0</u>	<u>4.5</u>		

Date 10.2.80

Tester _____

DRY CYCLE SUMMARY

(For deviation attach supplementary sheet)

Previous Cycles 17500

Cycle Rate _____

TEST: Life on - off Remarks 2

<u>2500</u> Cycles	Total <u>20000</u>			
Sear Lift <u>Life on - off</u>	<u>1007.5</u>		<u>mill full - .002</u>	
Trigger Pull <u>6.5</u>	<u>6.25</u>		<u>6.25</u>	
Observations:	Force for Safe On	Force for Safe Off	10 Rd. Function	Safe Operation
<u>(4.5)</u>	<u>4.5</u>	<u>4.5</u>	<u>3.75</u>	
<u>(4.0)</u>	<u>4.0</u>	<u>3.5</u>	<u>1.0</u>	
<u>(4.0)</u>	<u>4.0</u>	<u>3.5</u>	<u>3.1</u>	

_____ Cycles	Total _____			
Sear Lift _____	_____		_____	
Trigger Pull _____	_____		_____	
Observations:	Force for Safe On	Force for Safe Off	10 Rd. Function	Safe Operation
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

_____ Cycles	Total _____			
Sear Lift _____	_____		_____	
Trigger Pull _____	_____		_____	
Observations:	Force for Safe On	Force for Safe Off	10 Rd. Function	Safe Operation
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

_____ Cycles	Total _____			
Sear Lift _____	_____		_____	
Trigger Pull _____	_____		_____	
Observations:	Force for Safe On	Force for Safe Off	10 Rd. Function	Safe Operation
_____	_____	_____	_____	_____
_____	_____	_____	_____	_____

Date

10/2/51

Tester

P. Long

Page

1

DRY CYCLE SUMMARY

(For deviation attach supplementary sheet)

Previous Cycles

Cycle Rate

TEST:

A-1 - 77

Sample 2

<u>0</u> Cycles	Total <u>0</u>	
Sear Lift <u>1.009</u>	<u>huffel .0045</u>	
Trigger Pull <u>6.00</u>	<u>5.75</u>	
Observations:	Force for Safe On	Force for Safe Off
	<u>8.00</u> <u>9.00</u>	<u>6.00</u> <u>7.50</u>
	<u>9.00</u> <u>9.00</u>	<u>6.50</u> <u>7.50</u>
	<u>8.50</u>	<u>7.00</u> <u>(6.4)</u>
	10 Rd. Function	Safe Operation

<u>3140</u> Cycles	Total <u>3140</u>	
Sear Lift		
Trigger Pull <u>6.50-6.00-6.25</u>	<u>6.25-6.25</u>	
Observations:	Force for Safe On	Force for Safe Off
	<u>6.50</u> <u>6.50</u>	<u>7.00</u> <u>6.75</u>
	<u>6.50</u> <u>6.00</u>	<u>7.00</u> <u>7.00</u>
	<u>6.00</u>	<u>7.50</u>
	10 Rd. Function	Safe Operation

<u>1860</u> Cycles	Total <u>5000</u>	
Sear Lift		
Trigger Pull <u>6.50-6.50-6.50</u>	<u>6.50-6.25</u>	
Observations:	Force for Safe On	Force for Safe Off
	<u>5.00</u> <u>5.00</u>	<u>5.00</u> <u>5.00</u>
	<u>5.00</u> <u>5.00</u>	<u>5.00</u> <u>5.00</u>
	<u>4.75</u>	<u>5.00</u>
	10 Rd. Function	Safe Operation

<u>2500</u> Cycles	Total <u>7500</u>	
Sear Lift		
Trigger Pull <u>6.25-6.25-6.25</u>	<u>6.25-6.25</u>	
Observations:	Force for Safe On	Force for Safe Off
	<u>5.00</u> <u>5.00</u>	<u>5.00</u> <u>5.00</u>
	<u>5.00</u> <u>5.00</u>	<u>5.00</u> <u>5.00</u>
	<u>5.00</u>	<u>5.00</u>
	10 Rd. Function	Safe Operation