

Extractor	93712	A/U M/700	N/A	N/A	\$ 0.77	\$ 0.00
Ejector	300342	Purchase & Color	\$ -	\$ 900	\$ 0.16	\$ 0.00
Ejector Spring	????	Purchase	\$ -	\$ -	\$ 0.03	\$ -
Ejector Pin	94555	A/U M/700	N/A	N/A	\$ 0.01	\$ -
Bolt Assembly Pin	300330	Purchase & Color	\$ -	\$ 400	\$ 0.22	\$ 0.00
Firing Pin Assembly	????	Assemble	\$ 7,500	\$ 1,000	\$ 3.28	\$ 0.54
Bolt Plug	300368	Purchase	\$ -	\$ -	\$ 0.94	\$ -
Bolt Plug Insert	300346	Purchase	\$ 2,250	\$ 300	\$ 0.29	\$ -
Firing Pin	300334	Purchase & Color	\$ -	\$ 400	\$ 0.30	\$ 0.00
Firing Pin Tip	300335	Purchase & Heat T	\$ 1,000	\$ 1,100	\$ 1.28	\$ 0.02
Firing Pin Head	300336	MIM	\$ 25,500	\$ 8,900	\$ 0.33	\$ 0.26
Firing Pin Spring	????	Purchase	\$ -	\$ -	\$ 0.14	\$ -
Front Sight	94084	A/U M/700	N/A	N/A	\$ 0.01	\$ 0.25
Front Sight Ramp	94657	A/U M/700	N/A	N/A	\$ 0.02	\$ 0.26
Front Sight Ramp Screws (2)	28505	A/U M/700	N/A	N/A	\$ 0.09	\$ 0.00
Rear Sight Assembly	103146	A/U M/700	N/A	N/A	\$ 0.28	\$ 0.91
Elevation Screw	90906	A/U M/700	N/A	N/A	\$ 0.02	\$ -
Rear Sight Aperture	94333	A/U M/700	N/A	N/A	\$ 0.00	\$ 0.08
Rear Sight Base	103531	A/U M/700	N/A	N/A	\$ 0.16	\$ 0.24
Rear Sight Slide	94335	A/U M/700	N/A	N/A	\$ 0.07	\$ 0.38
Windage Screw	90904	A/U M/700	N/A	N/A	\$ 0.02	\$ 0.00
Rear Sight Base Screw (2)	28505	A/U M/700	N/A	N/A	\$ 0.09	\$ 0.00
M/710 ESTIMATE - REV. 6 - CLASS 2 ESTIMATE						
Part #	Proposed	Capital	Operations	Material	Labor	

~AUTODATE