

July 14, 81
M1700 Firing pin - Firing pin head.

- Try sampler with end gap.
6 samples.
- Control - full cross pin.
hold back with washer.
assembler can check.
- Look into using trays.
- Rebuilding the fixture for operation
- Redesign & make ~~altering~~ alternate
Determine load.
alter fixture to preload
firing pin head.
- Firing pin head - hole alignment