

IX. Malfunctions Continued

<u>Remington M-700</u>	<u>No. of Rds.</u>	<u>Malf.</u>	<u>Rate</u>
30-06 Cal. ADL	0-500	None	0%
#B625032	501-1000	None	0%
	<u>1,000</u>	<u>None</u>	<u>0%</u>
243 Var. BDL	0-500	None	0%
#B6270650	501-1000	None	0%
	<u>1,000</u>	<u>None</u>	<u>0%</u>
7mm Rem. Mag.	0-500	1 - Action Bind	2.2%
#B6245077	501-1000	10 - Shell Jumps Mag.	0%
	<u>1,000</u>	<u>11</u>	<u>1.1%</u>
<u>Three Rifle Total</u>	<u>3,000</u>	<u>11</u>	<u>0.4%</u>
<u>Ruger M-77</u>			
30-06 Cal. #73-95020	0-500	None	0%
	501-1000	1 - Stem Low	0.2%
	<u>1,000</u>	<u>1</u>	<u>0.1%</u>
243 Var. #74-00086	0-500	None	0%
	501-1000	1 - Stem Low	0.2%
	<u>1,000</u>	<u>1</u>	<u>0.1%</u>
7mm Rem. Mag. #74-24449	0-500	None	0%
	501-1000	None	0%
	<u>1,000</u>	<u></u>	<u>0%</u>
<u>Three Rifle Total</u>	<u>3,000</u>	<u>2</u>	<u>0.2%</u>
<u>Smith & Wesson M-1500</u>			
30-06 Cal. #PN01129	0-500	1 - Stem High	0.2%
	501-1000	None	0%
	<u>1,000</u>	<u>1</u>	<u>0.1%</u>
243 Cal. #PN11952	0-500	None	0%
	501-1000	None	0%
	<u>1,000</u>	<u>None</u>	<u>0%</u>
7mm Rem. Mag. #PN02081	0-500	None	0%
	501-1000	None	0%
	<u>1,000</u>	<u>None</u>	<u>0%</u>
<u>Three Rifle Total</u>	<u>3,000</u>	<u>1</u>	<u>0.03%</u>