


VISUAL INSPECTIONS

3" Crack in tip.



Heavy Scratches
on Some Stocks.



Ruger Visual Insp.