sary, but should only be done when an objectionable buildup of fouling occurs or preparatory to storing the rifle for a long period. When cleaning the bore, it is good practice to insert the cleaning rod from the rear to avoid possible wear of the rifling at the muzzle.

INSTRUCTIONS FOR ORDERING PARTS

When ordering parts, please give the following information:

- 1. Model number of the firearm.
- 2. Serial number of the firearm.
- 3. Caliber and grade of the firearm.
- 4. Part name and number of the part required.

Please order parts separately from factory repair service or delivery may be delayed.

Send your order to:

Smith & Wesson 2100 Roosevelt Ave. Springfield, MA 01101 Attn: Parts Department

INSTRUCTIONS FOR FACTORY SERVICE

Should your Smith & Wesson long gun require adjustment, repair, or refinishing, we recommend most sincerely that the weapon be returned to the factory. There is no other way to insure that the work will be done in a properly equipped and staffed shop.

Charges are very reasonable, being based on the cost of parts replaced plus a labor charge for the time expended on the job. A labor charge for one hour is usually sufficient to cover all but very extensive overhaul jobs.

Long guns returned to the factory should be MARKED FOR THE ATTENTION OF THE SERVICE DEPART-MENT. A letter of instructions should be enclosed with the gun, and shipment by individuals must be Prepaid. Adherence to these suggestions will prevent loss of time in handling at the factory.

When your Long gun arrives for service, it will be very carefully inspected, together with your letter of instructions. Next, a quotation covering total cost of work to be performed will be sent to you. No actual work will be performed before receiving your approval of our quotation unless you specifically authorize us to do so.

THE SMITH & WESSON SPORTING GOODS GROUP PRODUCTS

- SMITH & WESSON AMMUNITION
- LEATHER GOODS
- HAND GUNS
- KNIVES

- PUMP SHOTGUNS
- AUTOMATIC SHOTGUNS
- CENTERFIRE RIFLES
- . AIR GUNS .



Springfield, Ma. 01101

0911-1500/1M/1 DRAFT

Printed in U.S.A.