

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

*Remington*  
REMINGTON

*PETERS*  
PETERS

Xc: C.B. Workman  
J.H. Carter  
J.P. Linde  
R.B. Sperling  
R.S. Murphy  
J.S. Martin  
R.J. Long

"CONFINE YOUR LETTER TO ONE SUBJECT ONLY" \_\_\_\_\_

Ilion, New York  
July 14, 1982

To: K.D. Green  
F.T. Millener

M/788 INSTRUCTION MANUAL  
SAFETY DETENT SYSTEM

Normally instruction manuals are not revised for changes regarding component appearances. Revision to the manual would be done at the time of the next printing. Immediate revisions are made for functional changes.


A M/788 new safety lever, safety detent plunger and safety detent spring were designed to replace the current parts in an effort to increase safety "off" forces. The function of the new system is identical to that of the current safety. The parts are not to be separated or interchanged with the current production parts. The new safety system can be used to repair rifles already in the field providing that the new system is installed in its entirety. This should eliminate the need to keep a supply of the current parts on hand. Listed are the parts that are affected:

	<u>New Part No.</u>	<u>Old Part No.</u>
Safety Lever	13913	14035
Detent Spring	92058	14498
Detent Plunger	92057	14497

Revision to the manual was reviewed with Legal and it is felt that revisions could be incorporated at the next printing. A supplement for the Field Service Manual will be prepared for distribution to our recommended gunsmiths.

Enclosed are sample parts together with a current instruction manual.

Should you have any questions, call me.

  
R.L. Sassone, Supervisor  
Project Control & Administrative Services

RLS:m  
Enclosures